

DEPARTMENT OF ASSETS, INFORMATION & SERVICES

	SUMMARY OF RECORDS REVIEW
Site Addresses and PINs:	PIN 25-22-107-001, -002, -003, -004, -032: 11201-11219 S Michigan Ave
	PIN 25-22-107-032 and 25-22-102-035: 11152-11232 S Edbrooke Ave
From:	Jessica Min Jun
Reviewed By:	Abby Mazza amm
Review Date:	February 10, 2021

The Department of Assets Information and Services (AIS) conducted a limited environmental screen (screen) for the 11201 to 11219 S Michigan Ave and 11152 to 11232 S. Edbrooke Ave (the Site). The City owns the two parcels on S. Edbrooke Ave (25-22-107-032 and 25-22-102-035) and the parcels on Michigan Ave are privately owned. The purpose of the screen is to evaluate the potential for an environmental concern for all addresses associated with the Site. The screen is conducted by reviewing historical land use resources and searching AIS records and publicly available environmental databases. An environmental concern is identified if there is the potential for impacts to the Site from onsite or adjacent non-residential land use or facilities included in reviewed information.

This screen identified past commercial uses at the Site addresses. Chicago Department of Public Health (CDPH) records indicate an underground storage tank (UST) is possibly located on the Site address 11201 S. Michigan Ave and two above ground storage tanks were removed from this address in 1994. CDPH records also identified USTs on properties adjacent to the Site. CDPH records also reported on-site fly dumping at 11200 S Edbrooke Ave; however, this is not an environmental concern because it is described as tires and debris. Sanborn Fire Insurance Maps indicated that printing and plating companies were located west of the Michigan Ave Site addresses and these operations pose a possible environmental concern.

AlS understands that the Department of Planning and Development is considering issuing a Request for Proposals for the redevelopment of the Site. The future use is not known at this time. Based on the screen findings, a Phase I Environmental Site Assessment (ESA) of the Site conducted in conformance with ASTM E- 1527-13 is required and must be performed within 180 days prior to acquisition or disposition. Based on the results of this screen, a Phase II subsurface investigation of the Site will also likely be required for all parcels. If the Phase II identifies contamination above applicable remediation objectives as determined by Title 35 of the Illinois Administrative Code Part 742, the Site, or portions thereof as approved by AIS, must be enrolled in the Illinois Environmental Protection Agency's Site Remediation Program and a comprehensive No Further Remediation Letter obtained prior to occupancy. If assessments are to be performed by others, a reliance letter naming the City of Chicago as an authorized user must be provided by the environmental professional.

Supporting Information

The following table summarizes the results of each record reviewed. Additional detail is provided in the attachments.

Record	Record Rev	view Results
Туре	On-Site	Adjacent
AIS Files	 2006 Property Screen for 11152 S Edbrooke Ave: CDPH records were included in the property screen; CDPH records are summarized in the last row of this table. 2009 Demolition Screen for 11200 S Edbrooke Ave: indicated orphan USTs may exist and illegal dumping at the property (described in the last row of this table). 2010 and 2012 NEPA Environmental Compliance Certification indicating the building on 11200 S Edbrooke Ave /11227 S Michigan Ave was approved for demolition. 	Not applicable.
Sanborn Fire Insurance Maps 1897-1950	 1897: Vacant land. 1911: Developed land between Michigan Ave and Curtis Ave just north and south of E 112th St. Commercial stores including an undertaker and steam laundry, south of 112th St and residential to the north of 112th St. 1939 -1950- Curtis Ave was renamed to Edbrooke Ave. Department stores with sub basements and a parking garage south of 112th St and parking located north of 112th St 	 North (north of 112th St): 1897 vacant land; 1939-1950 residential and commercial stores South (south on both Michigan Ave and Edbrooke Ave): 1939-1950 residential and commercial stores East (east side of Edbrooke Ave): 1939 -1950 residential West (west side of Michigan Ave): 1897 residential and commercial stores; 1911 commercial stores and offices; 1939 commercial stores and plating works 1950 commercial stores and printing location
CDPH Records	 11201 S Michigan Ave: two ASTs were found and removed in 1994; however, the UST that was being investigated was not located. 11200 S Edbrooke Ave: 1999 fly dumping of tires and debris. 11201 S Michigan Ave demolition completed in 2019 	 11151 S Michigan Ave: 1000-gallon fuel oil tank; 11155 S Michigan Ave: 1000- gallon fuel oil tank; 11200 S Michigan Ave: 1000-gallon fuel oil tank; 11218 S Michigan Ave: 1,000-15,000 fuel oil tank; 11211 S Edbrooke Ave: Auto repairs on site and oil dumping in the back of the garage and alley.

Attachments:

- 1. AIS Limited Environmental Screen Summary
- 2. AIS Records
- 3. Sanborn Maps available from Chicago Public Library
- 4. CDPH Records

AIS Limited Environmental Screen Summary

AIS's limited environmental screen includes a review of certain historical land use resources and environmental records (see below table) to determine if a site has a non-residential land use or potential environmental concern. This screen does not include a visual inspection and it cannot address the possibility of conditions existing on or near the site that would not be reasonably identifiable from the limited records searched summarized herein. This screen is not intended to identify all environmental information or documents relating to the site, nor does it constitute a warranty of any kind or replace a Phase I Environmental Site Assessment. AIS does not guarantee that a site that has been reviewed is completely free from environmental concerns. Future regulatory modifications or agency interpretations may potentially affect the compliance status of a site.

Record Type	Description	Use	Extent
AIS Files	Property screen, brownfield and National Environmental Policy Act (NEPA) review project files.	Evaluate existing environmental information AIS has in their project files for the site.	Onsite Only
Sanborn Fire Insurance Maps available from Chicago Public Library	Maps depicting historical property use.	Determine if there has been any non-residential use on the site or any environmental concerns associated with adjacent land use that could impact the site.	-
CDPH Records	This includes Chicago Department of Public Health records.	Evaluate the potential for on-site and adjacent facilities to impact the site based on nature of listing	Adjacent

Note: AIS did not order an EDR package of Sanborns, radius report, and City Directories.



REQUEST FOR AIS ENVIRONMENTAL SITE ASSESSMENT SERVICES

This form requests the environmental services listed in the table below. Please check <u>all</u> services anticipated for the Project and use one request form per Project. Multiple PINs and addresses are allowed (please attach additional pages as needed).

1201-11219 S. Michigan Ave/11152 -112 5-22-107-001, -002, -003, -004, -032, and 25 b be determined by Request for Proposal ase Describe Below): mental Site Assessment Report	-22-102-035 (-032 a		wned) _ Ward:	0th (D11-)
b be determined by Request for Proposal ase Describe Below):		nd -035 are City-o		
ase Describe Below):	D Dama dia		_ Ward:	Oth (Deede)
	D Damadia			9th (Beale)
Rehabilitation Privanmercial/Industrial 💽	(14D/7D Redevelo Real Esta (ANLAP NEPA Real Other En Funding Mec Corporat CDBG Funding Year -Owned ately-Owned Future Land) ppment/Sales A te Transaction , Large Lots, D eview (Identify vironmental Se hanism: e TIF HON Prop # Units aft Use: Commental	erty to be De ercial/Indus	4D) eview c.) (14D) 0D – 180D) be below) CHA Other molished ab
on Attached: Ig Project PINs (MANDATORY) Ils outlined/highlighted m ement Department of Planning and Developme Michael Penicnak	 Proposed of Draft Redo Title Searce 	development de evelopment Ag h and/or Title Req Tele Req	escription & p reement/Terr Insurance Co uest Date: ephone No.: uested Due	olans n Sheet
	vestigation Report (90D) nvironmental Documents vironmental requirements) (14D) emediation (NFR)/ Varies – Project Specific) Property Screen Request Form) Disposition Financial Assistance Existing Structure Rehabilitation Privation nmercial/Industrial vestigation and Development plans to RFP for t. The land is not contiguous (see PIN map). Is outlined/highlighted ment Department of Planning and Development Michael Punicnak	(14D/7D) vestigation Report (90D) Redeveloping Redeveloping Redeveloping Reduction (NFR)/ vironmental requirements) (14D) (ANLAP) emediation (NFR)/ NEPA Redveloping Reduction (NFR)/ Varies – Project Specific) Other Endition (NFR)/ Property Screen Request Form) Other Endition (NFR)/ Disposition Corporate Financial Assistance Funding Mechanic (Corporate) Rehabilitation Privately-Owned mmercial/Industrial Image: Future Land Reduction (Nerger) e of Work: Planning and Development plans to RFP for the above privately t. The land is not contiguous (see PIN map). on Attached: Proposed of mapping Proposed of mapping Proposed of mapping and Development Department of Planning and Development Title Searce Department of Planning and Development Michael Pinicnak	(14D/7D) vestigation Report (90D) Redevelopment/Sales A nvironmental Documents Real Estate Transaction vironmental requirements) (14D) (ANLAP, Large Lots, D mediation (NFR)/ NEPA Review (Identify Varies – Project Specific) Other Environmental Sec Property Screen Request Form) Other Environmental Sec Disposition Corporate TIF Financial Assistance Corporate Prop Rehabilitation Privately-Owned Prop Rehabilitation Privately-Owned # Units aft mmercial/Industrial Future Land Use: Commental Site Asset Is outlined/highlighted Proposed development data for the above privately-owned and City-ot Title Search and/or Title Department of Planning and Development Proposed development data for the above privately-owned and City-ot Tele Michael Planicnak Tele Tele	(14D/7D) restigation Report (90D) nvironmental Documents vironmental requirements) (14D) mediation (NFR)/ Varies – Project Specific) Property Screen Request Form) Other Environmental Service (descrifted in the service) Disposition Financial Assistance Existing Structure City-Owned Property to be De Rehabilitation Privately-Owned # Units after Const/Rehaming and Development plans to RFP for the above privately-owned and City-owned land for net. The land is not contiguous (see PIN map). Image Project PINs (MANDATORY) Is outlined/highlighted Mattached: Reproject PINs (MANDATORY) Department of Planning and Development Request Date:

30 N LaSalle St, Suite 300, 312.742.2565, ram.ramasamy@cityofchicago.org

VERSION DATE: 06/15/2020



2FM PROPERTY SCREEN REQUEST

Requesting Department:	
Request Date:	

Planning & Development	
1/12/2021	


Project Manager:	Michael Per	nicnak				
Contact Phone:	742-1337					
Anticipated Trans		Property	Size (acres):	2.01359045		
Requested Review	v Completion D	ate: 2/1/202	21	Ward:	9	
Property Transact	ion (circle one):		Acquisition	Dispo	osition	Other
Method (circle on	e):					
TRP Lie	en Foreclosure	Condemnati	on Nego	tiated Purchas	e/Sale Othe	r: <u>RFP</u>
Project Name: _	RFP of Forme	r Gately Pec	ple's Store	Site		
Property Site Add	ress(es): 112	01-11227 S.	Michigan A	Ave/11152 S	S. Edbrooke	Ave.
PIN Number(s):	25-22-107-0	01, -002, -0	03, -004, -0	32, and 25-	-22-102-035	
	Please inclu	de a Zoning N	1ap w/ parcel	s outlined/hi	ghlighted	
Current Property	Owner (Circle C	One):	City	Pri	vate	
Future Property O	wner (Circle Or	ne):	City	Pri	vate	
City Involvement	(i.e., TIF fundir	ng, etc.) Inc	entive packa	age to be de	etermined	
(Check all that appl	y and provide det	ails in Addition	al Information	below)		
Property Use	Industrial	Commercial	Residential	Mixed-Use	Open Space	Other (specify)
Current		Х				Vacant land
Future		Х		Х	2	
Historical		Х		Х		
Provide maps and other useful documents that may facilitate the Property Screen Process. Does the buyer/seller already have a Phase I ESA, Phase II ESA, Sampling Report, or other environmental information? If yes, please provide.						
Additional Inform	ation:					
Zoned Use: <u>N</u>	/1-1 and B1-3	X	Surrounding I	Land Use:	Commercial	and residential
Status of Site (circle one):	Occupied w/		cupied w/o stru (e.g. Parking L		ant Abando	ned w/structures


Please direct the completed form and any questions or comments regarding this property screen to Kimberly Worthington of the Chicago Department of Fleet and Facility Management (744-9139) at <u>Kimberly.Worthington@cityofchicago.org</u> or 30 N. LaSalle St., Suite 300.

÷.

11201-27 S Michigan Ave/11154 S Edbrooke Ave







Cook County GIS Dept

ZONING MAP



LEGEND



RFP Site

Zoning District Boundary

REQUEST FOR DOE PROPERTY SITE ASSESSMENT SERVICES

To:	Kimberly Worthington,	Deputy (Commissioner,	Department	of the Environme	ent
-----	-----------------------	----------	---------------	------------	------------------	-----

Service	Requested:
---------	-------------------

- Property Acquisition Screen
 - **Q** Review of Environmental Reports
 - □ Remediation Cost Evaluation
 - Phase I Environmental Site Assessment
 - □ Phase II Subsurface Site Investigation
 - □ Federal NEPA Environmental Assessment
 - □ No Further Remediation Letter Services
 - □ Special Project Services (Please describe on separate page)

Property Site Address:	TRP Site (See attached)
PIN Number:	Ward Number:
Requesting Department:	
Project Manager:	Telephone Number:
Authorization:	Date:

(Commissioner/Deputy Commissioner)

Additional Supportive Documentation (attached if project appropriate):

- □ Completed F-18 form
- □ Right of Entry Agreement
- Environmental Site Assessment reports
- □ Parcel map
- Proposed development plans
- □ Property Acquisition Screen Request form

THIS SPACE FOR DOE USE ONLY

Date Received:	2/8/06	_ Date Completed: 3-27-06
DOE Project Manager:	A. Ahumada	·
DOE Project File Number	: 1337	
Comments:		
Delivered 3-7	8-06	

FILE COPY



a - 15 - F Jan Milly

1.13 3.17

NOF CHICAGO	PROPER	CITY OF FY ACQUIS	CHICAG		EQUEST
Charles and the second	Request Date:	Department:	2-6-()6	
Project Manager:	Stacy	Haski	ns_		
Contact Phone:	2-05	10			
Anticipated Acquisition Date:	AMT	U		Project Size:	
Requested Review Completion Date:					
Method of Acquisition (circle	one):				
TRP Lien I	Foreclosure C	Condemnation	Negot'd Purc	hase O	ther
	ν.				
Project Address (es) & PIN (s)	,	122-02	5		
(Include all possible	00-00-	Talkane	\sim		
addresses and/or PINs)	mod 2	· CADION	C		
(Check all that apply) 🖌			111-CAL112		
Property Use	industrial	commercial	residential	mixed-use	other (specify)
Current					
Future		~		~	
Historical					
Historical research conducted should Provide maps and other useful document	I be complete up to and ments that may facilitate	including 1890. the Acquisition Scree	ning Process		
Additional Information:					
Zoned Use:		Surroundi	ng Land Use:	<u>\</u>	
Status of Site (circle one):	Occupied w/s	tructures Parkin	g Lot Vacan	Abando	ned w/structures
Please direct the completed form and Environment (744-8908) at 30 N. Las	any questions or comme Salle St., 25 th Floor.	ents regarding this acq	uisition screen to Cl	aire Woolley of the	Chicago Department of

÷

CITY OF CHICAGO PROPERTY ACQUISITION SCREEN REQUEST

11152 S Edbrooke (Site Address)

Database	On-Site Records	Records for Neighboring Sites
DOE Underground Storage Tanks	none	see attached
DOE Complaints		
DOE Inspections		
DOE Enforcement		
DOE Pollution Prevention		
IEPA Site Remediation Program Status	monl	more
IEPA Leaking Underground Storage Tank Program Status		see ottached
Manufactured Gas Plant History (1/4 mile radius search)	mone	Mone
USEPA Cleanups (Enviromapper last updated 5/04)		See attached
Comments		100 - year flood zone approximately 300'E See zone designation A.

CITY OF CHICAGO PROPERTY ACQUISITION SCREEN REQUEST

11152 S. Edbrooke **Acquisition Screening Results:**

Environmental work anticipated to be conducted:

Environmental Site Assessment Sampling Investigation Site Clean-Up/Remediation

If anticipated work exceeds \$250,000, including cleanup, project site is considered a high environmental liability and risk for acquisition.

M

Anticipated work will incur....


2 AND		Less than \$ Equal to or		\$250,000	
Compiled by: Verified by: Comments:	\supset	Date:	<u>3/27</u>]	116	
				ж	

Past and present conditions were considered on the basis of agency records. Asbestos, radon, lead-based paint, lead in drinking water and impact on wetland surveys were not a part of this review. In addition, most sites have not been visually inspected due to the high volume of sites to be screened

This report cannot address the possibility of conditions existing on or near the site that would not be reasonably identifiable from the Databases Search. Although this report was prepared with due care, it does not constitute a warrantee of any kind. DOE does not guarantee that the Site is completely free from environmental concerns. Future regulatory modifications or agency interpretations may potentially affect the compliance status of the site.

Sites where acquisition can proceed without the completion of environmental work indicates that DOE considers the site to be of low environmental risk and liability to the City. Environmental conditions may exist which the screening process did not identify.

For Internal (City of Chicago) Use Only



37-14-220 N. I. B. L. 25 - 22

"A " SUB. of the W. 1/2 of the N.W. 1/4 of Sec. 22-37-14 by Royal Tax Assessor for the Town of Worth. Rec. Aug. 26, 1857. Doc. 90844. "B"

SUB. of Lot 3 in Assessor's Div. of the W. 1/2 of the N. W. 1/4 of Sec. 22-37-14. Rec. July 16, 1870. Doc. 59716. Re-rec. Jan. 22, 1872. Doc. 10046. "C"

SUB. of 1/2 ac. of land commencing 15 cbs. S. and 0.33 chs. E. of the N.W. corner of Sec. 22-37-14, thence E. 2.50 chs., thence N. 2.00 chs., thence W. 2.50 chs., thence S. 2.00 chs., to beginning. Rec. May 14, 1877. Doc. 134714. "D"

SUB. of that part of Lot 1 of Assessor's Div. of the W. 1/2 of the N. W. 1/4 of Sec. 22-37-14 lying W. of Thornton Rd. Rec. Apr. 26, 1881. Doc. 322472. "E"

E. STANWOOD'S SUB. of the S. 1/2 of the S. 1/2 of the S.W. 1/4 of the N.W. 1/4 of Sec. 22-37-14. Rec. Apr. 27, 1881. Doc. 322805.

"F" DYKS ADD. TO PULLMAN, a sub. of Lot 2 of Assessor's Div. of the W. 1/2 of the N. W. 1/4 of Sec. 22-37-14. Rec. May 29, 1882. Doc.

398745. "G" REICH'S SUB. of part of Sublot 3 of Lot 3 in Assessor's Div. (see "B"). Rec. Dec. 9,

1885, Doc. 675400. THO

KIONKA'S SUB. of Lots 1 & 2 in Sub. of Lot 3 In Assessor's Div. (see "B"), Rec. Sept. 15. 1887. Doc. 872083. 1.70

SUB. of Lot 4 in Sub. of Lot 3 in Assessor's Div. (see "B"). Rec. Dec. 2, 1887. Doc. 900557.

ייאיי E. STANWOOD'S SUB. of Lots 1 to 11, both Incl., in Blk. 1, together with the E. 7 ft. of State St. lying W. and adj. said lots, and the 16 ft. alley lying E. and adj. said lots in E. Stanwood's Sub. (see "E"). Rec. Apr. 13,

"L" RESUB. of Lots 28 to 36 incl. of Blk. 3 in Sub. of Lot 4 in Sub. of Lot 3 of Assessor's Div. (see "B"). Rec. Oct. 5, 1888. Doc. 1012727. "M"

BCHAFER'S ADD. TO PULLMAN, in the W. 1/2 of the N.W. 1/4 of Sec. 22-37-14. Rec. Oct. 12, 1892. Doc. 1749715. Vacation of above rec. Jan. 17, 1895.


"N"

SCHAFER'S ADD. TO PULLMAN in the W. 1/2 of the N. W. 1/4 of Sec. 22-37-14. Rec. Sept. 3, 1897. Doc. 2583885. "0"

PFOTENHAUER'S SUB. of that part of Lot 3 lying between Michigan & Indiana Aves. of Lot 3 in Assessor's Div. (see "B"). Rec. Mar. 22, 1899. Doc. 2797301. ייסיי

EGAN'S ADD. TO ROSELAND, a sub. of part of Lot 1 of Assessor's Div. of the W. 1/2 of the N.W. 1/4 (see "A"). Rec. Oct. 4, 1902. Doc. 3302975.

W. 1/2 N. W. 1/4 Sec. 22-37-14 HYDE PARK TWP.



					222	I. ANV	- AN	0	L.	3	8		c	, tot	- Charles	لمن ^م ر مار م	~~~				1. 					N'W .	210141	N S	0							
DISTANCE	77	77	84				316					403	421	438	455	466	487	497	499	499	526	549	553	568	605	615	617	627	629	630	651	653	656	665	674	679
AST	z	z	z	z	z	z	z	z	z	z	z	Z	X	N	N	z	z	z	z	A	N	z	z	z	z	z	z	z	z	z	z	Z	Z	z	z	z
Bldg Installation	z	z	z	z	z	z	z	z	z	z	z	z	z	z	XX	1 7	z	z	z	z	z	1	z	z	z	z	z	z	z	z	z	z	z	1 1	z	z
New UST_Bldg Ir	z	z	z	z	z	7	z	Y	z	z	Y	z	z	z	z	z	z	z	z	Y	z	z	z	z	z	٢	٢	Y	z	z	7	z	z	z	z	z
UST	z	z	z	z	z	z	z	z	γ	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	Z	z	z
Demo_Permi	z	Y	Y	z	γ	z	z	z	z	γ	z	٢	z	z	z	z	Υ.,	Y	Y	z	z	z	٢	z	Y	z	z	z	Y	z	z	z	γ	z	Y	z
P2	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	N	z	z
Enforce	7	z	z	z	z	z	Y	z	z	z	z	z	z	Y	z	z	z	z	z	z	z	z	z	7	z	z	z	z	z	z	z	z	z	z	z	Y
Inspection	7	Y	z	z	z	z	Y	z	z	z	7	Y	z	Y	z	z	z	z	z	z	Y	z	z	Y	z	z	z	z	z	z	Y	Y	Y	z	Z	Y
Compliant	Υ.	z	z	Y	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	γ	z	z	z	z	z	z	Z	z	Υ	Y	Z	z	z	Z	z
Address	11200 S EDBROOKE AV	11200-32 S EDBROOKE AV	11153 S EDBROOKE AV	11211 S EDBROOKE AV	11221 S EDBROOKE AV	11151 S MICHIGAN AV	11147 S MICHIGAN AV	11155 S MICHIGAN AV	11201 S MICHIGAN AV	11120 S EDBROOKE AV	11200 S MICHIGAN AV	11117 S EDBROOKE AV	11140-42 S MICHIGAN AV	11219 S MICHIGAN AV	11121 S MICHIGAN AV	11218 S INDIANA AV	11236 S EDBROOKE AV	11117 S MICHIGAN AV	11120-22 S MICHIGAN AV	11218-24 S MICHIGAN AV	11226 S INDIANA AV	11224 S MICHIGAN AV	11114-16 S MICHIGAN AV	11232 S MICHIGAN AV	11247 S EDBROOKE AV	11108 S MICHIGAN AV	11105 S MICHIGAN AV	132 E 111TH ST	128 E 111TH ST	126 E 111TH ST	150 E 111TH ST	34 E 112TH PL	24-34 E 112TH ST	11242 S MICHIGAN AV	156 E 111TH ST	11102 S MICHIGAN AV

3/15/2006

11152 S EDBROOKE

* only demo permitts wi Acm removere zue previded in

Total Records: 36

-

1200 S Edbrooke Ward: 09	Zipcode: 60628 Police: 05 LPC: 0316495123
OMPLAINTS	
	Handled By 67 Gray, Darrell
open space dock in area.	
ISPECTIONS	
Inspection: 11/4/1999 Time: PM 12:14 By: 67 , Gray Comments:	Type: A5 - Illegal Dump Name of Site:
Inspection: 11/15/1999 Time: PM 03:15 By: 67 , Gray Comments:	Type: A5 - Illegal Dump Name of Site:
Inspection: 12/1/1999 Time: PM 03:36 By: 67 , Gray Comments: Found site to have apprx 40 peroperly owner.	Type: A5 - Illegal Dump Name of Site: - 50 cu yds of dumped waste material. Waiting for title search of
By: 67 , Gray	Type: A5A - Illegal Dump (State Open-Dump) Name of Site: Sang Wook RA te material. Waiting for title search of property owner to continue further
Inspection: 12/20/1999 Time: PM 12:41 By: 67 , Gray Comments: Drop off posted sign	Type: A5 - Illegal Dump Name of Site:
By: 67 ,Gray	Type: A5 - Illegal Dump Name of Site: n on pole located at westside of dock area.
By: 67 ,Gray	Type: A5A - Illegal Dump (State Open-Dump) Name of Site: Sang Wook RA ved accumulation of debris, rubbish, garbaage etc.
Inspection: 2/24/2000 Time: AM 11:00 By: 67 , Gray Comments: Owner respondent for remo	Type: A5A - Illegal Dump (State Open-Dump) Name of Site: Sang Wook RA val nuisance violation penalty.
Inspection: 4/7/2000 Time: AM 08:10 By: 67 , Gray Comments:	Type: A5 - Illegał Dump Name of Site:

š - 3

11200 S Edbrooke	Ward: 0	9 Zipcode:	60628 Police:	05 LPC:	0316495123	
Inspection: 11/16/2000 By: 85 , Kay Comments: Demo no a			- Demo/NESHAPS iite: Demo Site			
Inspection: 9/19/2001 By: 67 , Gray Comments: No illegal d	/	1:15 Type: A8 Name of S	- Site Assesment Site:			7
Inspection: 10/30/2001 By: 67 , Gray Comments: No dumpin	/	0:49 Type: A5 Name of S	* .		ň	
ENFORCEMENT						
Enforcement Date: 1/2 Company: Ra Mail Address: 112 Issued By: 1st Court Date: Disposition: - Comments:	, Sang Wook	Served: Sang ke Chicago, II Last Court D	Wook Ra 60628	Total Hearir	ngs:	
TICKET	DOCKET	CHARGE		DESCRIPTIC	NC	LIABLE
Enforcement Date: 2/2		orcement Type: Served: Ra Sa	ADM - Adminsitrativ	e Hearings		12 C
Mail Address: 112 Issued By: 67	200 S Edbroo 7 ,Gray	ke Chicago, II	60628			
1st Court Date: 3/ Disposition: AH		Last Court E	Date: Fine: \$1,500.00	Total Hearin	ngs:	
Comments:			The. \$1,500.00			
TICKET	DOCKET	CHARGE		DESCRIPTIC	ON	LIABLE
405344	00-80177	7-28-450	Owner responsible	e for nuisan	ce	L
405344	00-80177	7-28-720	Accumlate junk at	racting rats		L

11200 S Edbrooke

COMPLIANTS: 1 INSPECTIONS: 12 ENFORCEMENT: 2

11200-32 S Edbrooke Ward: 09 Zipcode: 60628 Police: 05 LPC: 0316495123

COMPLAINTS

INSPECTIONS

Inspection: 3/11/1999 Time: PM 02:25 Type: A9 - Demo/NESHAPS By: 68 ,Rodriguez Name of Site: Demo Site

Comments: Demo in progress just starting barriers & safe guards being set up.

Inspection: 11/20/2000Time: PM 03:15Type: A9 - Demo/NESHAPSBy:85,KayName of Site: Demo SiteComments: Demo in progress. Bldg. 100% down water tower removed.

ENFORCEMENT

11200-32 S Edbrooke

COMPLIANTS: 0

:0 INSPECTIONS:2

11200 S Michigan	Ward: 09	Zipcode: (60628 Police:	05 LPC:	
COMPLAINTS INSPECTIONS					
Inspection: 10/18/1999 By: 67 , Gray Comments:		7 Type: A8 - Name of Si			
ENFORCEMENT					
11200 S Michigan	COM	PLIANTS:0	INSPECTIONS	:1 ENFORCEMENT:0	

11117 S Edbrooke Ward: 09 Zipcode: 60628 Police: 05 LPC:

COMPLAINTS INSPECTIONS

× ¥

Inspection: 8/30/2002 Time: AM 08:05 Type: A9 - Demo/NESHAPS By: 85 , Kay Name of Site: Demo Site Comments: Demo 100% down.

ENFORCEMENT

11117 S Edbrooke

COMPLIANTS: 0

INSPECTIONS: 1

11219 S Michigan

Zipcode: 60628 Police: 05 LPC:

COMPLAINTS INSPECTIONS

Inspection: 4/3/1998 Time: PM 01:01 Type: A10 - Building Recycling Program By: 56 , Kelly Name of Site: Giant Beauty Supply Comments: For failure to establish an effective recylcing program in commercial establishments.

Inspection: 10/13/1998Time: PM 12:08Type: A10 - Building Recycling ProgramBy: 47WalshName of Site: Giant Beauty Supply

Ward: 09

Comments: Company is in compliance. Observed dumpster for OCC 7 BBs for glass & cans.

ENFORCEMENT

Enforcement Date: 4/3/1998 En	forcement Type:	ADM - Adminsitrative Hearings						
Company: Giant Beauty S	upply Served:	E. Park, Manager						
Mail Address: 11219 S Michig	jan Chicago, Il	L 60628		l.				
Issued By: 56 ,Kelly								
1st Court Date: 4/30/1998 Last Court Date: Total Hearings: 1.00								
Disposition: AH VC - CLOS	ED	Fine: \$50.00	0					
Comments:			2.40					
TICKET DOCKET	CHARGE	DESCRIPTION	LIABLE	1				
400147 9880072	11-5-023	Commercial Bldg recycling program						

11219 S Michigan

COMPLIANTS: 0

INSPECTIONS:2 EN

.

11226 S Indiana	Ward: 09	Zipcode: 6062	28 Police: 05 LPC:
COMPLAINTS			
Recieved: 6/7/2000 Site Name: Residentia Ticket No: Comments: Above gro determine	Court D ound storage (a	ate:	EScode: 14 - UST Handled By 30 Garcia M, Martin for the presence & leakage of any tank at above location I e.
NSPECTIONS Inspection: 6/8/2000	Time: PM 03:	00 Type: A7 - U	JST (Complaint)
By: 30 , Gar		Name of Site	

ENFORCEMENT

Comments:

11226 S Indiana

COMPLIANTS: 1

INSPECTIONS:1

11232 S Michigan

Zipcode: 60628 Police: 05 LPC:

COMPLAINTS INSPECTIONS

Inspection: 4/3/1998 Time: PM 01:00 Type: A10 - Building Recycling Program By: 56 , Kelly Name of Site: Star Shoes Chicago Comments: For failure to establish an effective recycling program in commercial establishments.

Ward: 09

ENFORCEMENT

Enforcement Date: 4	/3/1998 Enf	orcement Type:	ADM - Adminsitrative Hearings		
Company: S	tar Shoes Chic	ago Served: I	Myung Yang, Owner		
Mail Address: 1	1232 S Michiga	an Chicago, IL	60628		
Issued By:	56 ,Kelly				
1st Court Date: 4	4/30/1998	Last Court [Date: Total Hearings:	1.00	
Disposition: A	H DA - CLOSE	D	Fine:		
Comments:					
TICKET	DOCKET	CHARGE	DESCRIPTION		LIABLE
400146	9880075	11-5-023	Commercial Bldg recycling program		
e					

11232 S Michigan

COMPLIANTS: 0

S: 0 INSPECTIONS: 1

126 E 111TH ST Ward: 09 Zipcode: 60628 Police: 05 LPC:

COMPLAINTS

Recieved:4/16/199609:19 AM Taken By: KJEScode: 15 - Dumping (Solids)Site Name:A Wrecking Co.Handled By 25 Walker, MosesTicket No:Court Date:Comments:Left bucks into complainant's drive-way demo bldg. see telphone record.

INSPECTIONS ENFORCEMENT

126 E 111TH ST

COMPLIANTS: 1

INSPECTIONS: 0

Recieved: 7/10/2003	AM 10:20 Tal	aken By: BC EScode: 07 - Hazardous Material
ite Name: Vacant Lo	t	Handled By 55 Sheahan, Terrence
Ticket No:	Court Da	Date:
Comments: A metal ga	as tank was durr ank on the vaca	Imped in a vacant lot and needs to be disposed of. Inspector observed a larg ant lot next to the alley. Inspector removed the tank and brought it to the DO
Properto a		
NSPECTIONS		:45 Type: A8 - Site Assesment
NSPECTIONS	Time: PM 01:4	:45 Type: A8 - Site Assesment Name of Site: Vacant Lot

Comments: Site Clean.

ENFORCEMENT

150 E 111TH ST

COMPLIANTS: 1

INSPECTIONS: 1

34 E 112TH PL Ward: 09 Zipo	code: 60628 Police: 05 LPC:
COMPLAINTS INSPECTIONS	
Inspection: 10/12/2001 Time: PM 01:05 By: 35 , Kaehler Comments: Ald Office	Type: A8 - Site Assesment Name of Site:
Inspection: 9/13/2005 Time: AM 11:05 By: 82 , Adesanya Comments: 11th Ward Office.	Type: M - Meeting Name of Site:
Inspection: 11/4/2005 Time: PM 02:15 By: 35 , Kaehler Comments:	Type: A8 - Site Assesment Name of Site:
ENFORCEMENT	

34 E 112TH PL

.

COMPLIANTS: 0 INSPECTIONS: 3 ENFORCEMENT:0

24-34 E 112TH ST Ward: 09 Zipcode: 60628 Police: 05 LPC:

COMPLAINTS INSPECTIONS

 Inspection: 12/31/1997 Time: PM 12:45 Type: A9 - Demo/NESHAPS

 By: 42 , Rowder (#70 4/99)
 Name of Site: Demo Site

 Comments: Demo in progress.

 Inspection: 1/12/1998 Time: PM 03:35 Type: A9 - Demo/NESHAPS

 By: 42 , Rowder (#70 4/99)

 Name of Site: Demo Site

 Comments: Demo completed.

ENFORCEMENT

24-34 E 112TH ST

COMPLIANTS: 0

ANTS: 0 INSPECTIONS: 2

11102 S Michigan Ward: 09 Zipcode: 60628 Police: 05 LPC:

COMPLAINTS INSPECTIONS

Inspection: 4/3/1998Time: PM 12:00Type: A10 - Building Recycling ProgramBy: 56, KellyName of Site: City SportsComments: For failure to establish an effective recycling program in commercial establishments.

Inspection: 10/13/1998 Time: AM 11:45 Type: A10 - Building Recycling Program By: 47 , Walsh Name of Site: City Sports

Comments: No written documentation is not in place must be comply by 10/23/98.

ENFORCEMENT

Enforcement Date: 4/3/1		•••	ADM - Adminsitrative Hearings						
Company: City	Sports Se	rved: Mr. Kim, N	Manager						
Mail Address: 1110	02 S. Michig	an Chicago, IL	. 60618						
Issued By: 56 ,Kelly									
1st Court Date: 4/30/1998 Last Court Date: Total Hearings: 1.00									
Disposition: AH	Disposition: AH VD - Fine: \$100.00								
Comments:			• 2						
TICKET	DOCKET	CHARGE	DESCRIPTION	LIABLE					
400148	400148 9880074 11-5-023 Commercial Bldg recycling program								
<u> </u>									

11102 S Michigan

COMPLIANTS: 0

0 INSPECTIONS:2

Underground Storage Tank FREEDOM OF INFORMATION AS OF Friday, March 17, 2006

 FACILITY:
 Kang Won H
 Facility ID: 2036925
 IEMA Number: 0

 11201 S MICHIGAN
 CHICAGO, IL 60628
 WARD: 09
 CONTACT: MR WON H KANG
 PHONE:

 Owner:
 UNKNOWN
 1307 S WABASH
 CHICAGO IL 60605
 CONTACT: MR LEO FRONTERA
 PHONE: (312) 461-9600

TANK STATUS			SIZE	Material in Tank Install Date			Date Tank Last Used	
PERMIT	ТҮРЕ	ISSUED	COMPLETED	INSPECTED	CONTRACTOR & COMMENTS			
101042	ABANDON	06/24/1994		10/04/1994	SAFETY ENVIRONMENTAL CONSULTANTS TANK CAN NOT BE LOCATED.			

Comment Date	Comments
10/4/1994	THE TANK WAS NOT LOCATED. INSTEAD TWO ABOVE GROUND STORAGE TANKS WERE FOUND AND REMOVED.
10/11/00/	

ADDRESS:	11151 S M	ICHIGAN	LAST KNOWN SITE N	IAME: NEISNER I	DNOS ST	
DATE ISSUED	BUILDING PERMIT		COMMENTS			WORK BY
9/29/1954	119255	INSTALL 1-	1K GAL FUEL OIL TANK	FINAL 6/8/55	W & E	3 TAUB COMPANY

ADDRESS: 11155 S MICHIGAN LAST KNOWN SITE NAME: THREE SISTERS STORE

DATE ISSUED	BUILDING PERMIT	COMMENTS		WORK BY
9/23/1947	354729	INSTALL 1-1K GAL FUEL OIL TANK	FINAL 9/26/47	WATER TUBE BOILER & TANK

ADDRESS	11200 S M	ICHIGAN LAST KNOWN SITE NAME: NATIONAL CLOTHING
DATE ISSUED	BUILDING PERMIT	COMMENTS WORK BY
8/12/1955	178046	INSTALL/ENCLOSE 1-1K GAL FUEL OIL TANK FINAL N/G WATER TUBE BOILER & TANK

ADDRESS:	11218-24 \$	6 MICHIGAN	LAST KN	OWN SITE	NAME:	J. C. P	ENNEY	COMPANY
DATE ISSUED	BUILDING PERMIT		C	OMMENTS				WORK BY
2/9/1950	388961	INSTALL 1-15K	GAL FUEL	OIL TANK	FINAL	_ 10/13/5	io s	SUMNER S. SOLLITT & COMPA

ADDRESS:	11108 S M	ICHIGAN LAST KNOWN SITE NA	ME: MEDICAL ART	BUILDING
	BUILDING PERMIT	COMMENTS		WORK BY
12/12/1946	344475	INSTALL 1-2K GAL FUEL OIL TANK	FINAL 1/16/47	MOSBECK OIL EQUIPMENT

1.02

ADDRESS: 11105 S MICHIGAN LAST KNOWN SITE NAME: SPIEGELS INC.

DATE ISSUED	BUILDING PERMIT	COMMENTS		WORK BY
12/21/1948	372591	INSTALL 1-1500 GAL FUEL OIL TANK	FINAL 12/21/48	ENTERPRISE HEAT & POWER

THE FOLLOWING LIST ARE OLD BUILDING DEPARTMENT PERMITS ISSUED FOR UNDERGROUND STORAGE TANK WORK PRIOR TO 1/1/1993

DDRESS:	132 E 111	'H ST LAST KNOWN SITE NAME: CHAR H. BRAND	T & COMPANY
DATE ISSUED	BUILDING PERMIT	COMMENTS	WORK BY
12/8/1949	386908	INSTALL 1-1.5K F.O.	C.H. BRANDT JR

THE FOLLOWING LIST ARE OLD BUILDING DEPARTMENT PERMITS ISSUED FOR UNDERGROUND STORAGE TANK WORK PRIOR TO 1/1/1993

ADDRESS:	150 E 1111	TH ST LAST KNOWN SITE NAME:	DR WASS & SMITH
DATE ISSUED	BUILDING PERMIT	COMMENTS	WORK BY
12/6/1954	474699	INSTALL 1-1K F.O.	JOHN NELSON


(AST) FREEDOM OF INFORMATION REQUEST AS OF: 3/17/2006

- FACILITY: RETAIL/JOON K LEE (11140S.MICH) 11140-42 S MICHIGAN CHICAGO, IL 60628 CONTACT: MR LEE PHONE: (773) 468-3936
- OWNER: JOON K LEE LEE PHONE: (773) 468-3936 208 N WATERFORD DRIVE PROSPECT HEIGHTS, IL 60070

OF ASTS: 2.00 SIZES: 2-275 GALLON TYPE: PRODUCT: HEATING OIL

1/20/98: REMOVED 2-275 GALLON HEATING OIL TANKS. BOTH TANKS WERE IN GOOD CONDITION.NO CONTAMINATION FOUND.CEMENFT FLOOR NO BACKFILL.

Permit	Permit Type/Contractor	Tanks	Tank sizes	Recieved	Inspected	Issued	Effective	Completion
1	REMOVAL R.W.COLLINS CO	-	275 GALLON HEATING OIL REMOVED TANKS.NO CONTAMINATION FOUND.		11/20/1997	11/26/1997	12/8/1997	1/20/1998



Page 1 of 1

		Ilinois Envir Protection A	onment gency	al Rod R. Blag
L.I.T. Search				
IEMA # S	911600	LPC # 031649504	13	IEMA Date: 6/12/1991
Site:	YMCA	12		
Address:	4 East 111th St.			
	Chicago, IL. 60628		County: Co	ook
Regulated by:	731			
Products:	Jet Fuel			
20 Day Rpt:	4	<u>5 Day Rpt:</u>		
Project Manager:	NOT ASSIGNED			
Phone:		Email:		
Tank Operator	General	TACC) Clai	ms Search

Copyright © 2003 Illinois EPA Agency Site Map | Privacy Information | Kids Privacy | Web Accessibility | Agency Webmaster

22

		X Rod R.
. Search		
IEMA # 992547	LPC # 0316505015	IEMA Date: 11/13/1999
Site: South Side Colleg	e Prep.	
Address: 250 East 111th St.		
Chicago, IL. 60628	3 <u>Cour</u>	nty: Cook
Regulated by: 732		
Products: Other Petroleum		
20 Day Rpt:	45 Day Rpt: 4/27/2000	NFR Date: 6/29/2000
	<u>19</u>	Recorded: 10/16/2000
Project Manager: James Ransdell		
<u>Phone:</u> (217) 557-6938	Email: James.Ransdell@	epa.state.il.us

Copyright © 2003 Illinois EPA Agency Site Map | Privacy Information | Kids Privacy | Web Accessibility | Agency Webmaster

 \mathbf{r}_{i}

			Environ on Agen		Rod R. Bla
L.I.T. Search					
IEMA #	903598	LPC # 03	316495033	IEMA D	ate: 12/4/1990
Site:	Illinois Bell Teleph	none			
Address:	65 West 113th Pl.				
	Chicago, IL. 6062	8	Co	<u>unty:</u> Cook	
Regulated by:	731		ş		
Products:	Diesel				
20 Day Rpt:		45 Day Rpt:		NFR D	ate: 5/4/2004
				Record	<u>ded:</u> 11/5/2004
Project Manager:	Valerie Davis				
Phone:	(217) 785-7492	Email: \	/alerie.Davis@	epa.state.il.us	
Tank Operator	General	Title XVI	TACO	Claims	Search

Copyright © 2003 Illinois EPA Agency Site Map | Privacy Information | Kids Privacy | Web Accessibility | Agency Webmaster

24

	10	- Protect	ion Agen	су	Rod R. I
T. Search	с °с				
IEMA #	960704	LPC # (0316500008	IEMA D	ate: 4/30/1996
Site:	Tadros, Musa				
Address:	11442 South Mi	chigan Ave.			
	Chicago, IL. 606	628	Cou	i nty: Cook	
Regulated by:	732				
Products:	Used Oil				
20 Day Rpt:	5/16/1996	<u>45 Day Rpt:</u> 4	/2/1997	NFR Da	ate: 1/27/1998
				Record	ed: 10/21/1998
Project Manager:	Blumhorst			2	
Phone:		Email:	-		
		Title XVI	TACO	Claims	Search

Copyright © 2003 Illinois EPA Agency Site Map | Privacy Information | Kids Privacy | Web Accessibility | Agency Webmaster




All rights reserved. Use Subject to License/Copyright

These directions are informational only. No representation is made or warranty given as to their content, road conditions or route usability or expeditiousness. User assumes all risk of use. MapQuest and its suppliers assume no responsibility for any loss or delay resulting from such use.

SS=11152 SEObrooke distance = . 89 miles > . 25 miles not located with in search radius (1/4 mile)

MGP Site Search



SS=11152 SEdbrooke

	CITY OF CHICAGO DEMOLITION SCREEN RESULTS Results Do Not Substitute for Environmental Site Assessments
	Compiled by: Robyn West
RATED 4th MAY	Verified by: Zach Clayton
	Date: 10/21/2009
Project Name: _11200	S. Edbrooke Demo
Property Site Address(es	: 11200 S. Edbrooke
PIN Number(s): 25-2	2-107-032

Database Search Summary (Place mark in box if records attached):


Database Searched	On-Site	Neighboring	Database Searched On-Site Neighbori				
Chicago Department of Envir	onment		Illinois Environmental Protection Agency				
Underground Storage Tanks	_	_	Site Remediation	_	_		
(UST)			Program				
Complaints & Inspections	\boxtimes	\boxtimes	Leaking UST (LUST)				
Enforcement	\boxtimes	\boxtimes	IRID				
Pollution Prevention			State Sites Unit				
Permits			US Environmental Prot	ection Age	ncy		
Manufactured Gas Plants			Enviromapper				
Brownfields ID# 1337		\square	CERCLIS				

Comments: No known USTs on subject property. Orphan USTs may exist. Additional concerns

include illegal dumping activities at the property. A hazardous material survey should

be conducted prior to demolition.

Sites have not been visually inspected during the demolition screening process. This report cannot address the possibility of conditions existing on or near the site that would not be reasonably identifiable from the Databases Search. Although this report was prepared with due care, it does not constitute a warrantee of any kind. DOE does not guarantee that the Site is completely free from environmental concerns. Future regulatory modifications or agency interpretations may potentially affect the compliance status of the site.



ADDRESS	COMPLAINT	INSPECTION	ENFORCE	P2	DEMO_PERMI	UST_NEW	UST_BLDG	INSTALLATI	AST
11147 S MICHIGAN AV	N	Y	Y	Ν	Ν	N	N	N	Ν
11151 S MICHIGAN AV	N	N	N	Ν	N	N	Y	N	Ν
11153 S EDBROOKE AV	N	N	N	Ν	Y - No ACM	N	N	N	Ν
11155 S MICHIGAN AV	N	N	N	Ν	N	N	Y	N	Ν
11200 S EDBROOKE AV	Y	Y	Y	Ν	N	N	N	N	Ν
11200 S MICHIGAN AV	N	Y	N	Ν	N	N	Y	N	Ν
11200-32 S EDBROOKE AV	N	Y	N	Ν	Y - No ACM	N	N	N	Ν
11201 S MICHIGAN AV	N	N	Ν	Ν	N	Y	N	N	Ν
11211 S EDBROOKE AV	Y	N	Ν	Ν	N	Ν	N	N	Ν
11219 S MICHIGAN AV	N	Y	Y	Ν	N	Ν	N	N	Ν
11221 S EDBROOKE AV	N	N	N	Ν	Y - No ACM	N	N	N	Ν
11236 S EDBROOKE AV	N	N	N	Ν	Y - No ACM	N	N	N	Ν
11247 S EDBROOKE AV	N	N	N	Ν	Y - No ACM	N	N	Ν	Ν

see attached

on-site properties

ACM = asbestos containing material

On-Site Records

1200 S Edbrooke Ward: 09 Zipcode: 60628 Police: 05 LPC: 0316495123
COMPLAINTS
Recieved: 12/7/1999 AM 09:00 Taken By: EOB EScode: 15 - Dumping (Solids) Site Name: Sang Wook RA Handled By 67 Gray, Darrell Ticket No: Court Date: Comments: Fly dumping of tires & debris at the above loc. Garbage clothing, cardboard, boxes, & two tires dumped in open space dock in area.
NSPECTIONS
Inspection: 11/4/1999 Time: PM 12:14 Type: A5 - Illegal Dump By: 67 ,Gray Name of Site: Comments:
Inspection: 11/15/1999 Time: PM 03:15 Type: A5 - Illegal Dump By: 67 ,Gray Name of Site: Comments:
Inspection: 12/1/1999 Time: PM 03:36 Type: A5 - Illegal Dump By: 67 ,Gray Name of Site: Comments: Found site to have apprx 40 - 50 cu yds of dumped waste material. Waiting for title search of peroperly owner.
Inspection: 12/10/1999 Time: AM 11:13 Type: A5A - Illegal Dump (State Open-Dump) By: 67 ,Gray Name of Site: Sang Wook RA Comments: Approx 40-45 cu yds of waste material. Waiting for title search of property owner to continue further action & clean up.
Inspection: 12/20/1999 Time: PM 12:41 Type: A5 - Illegal Dump By: 67 ,Gray Name of Site: Comments: Drop off posted sign
Inspection: 1/20/2000 Time: PM 03:00 Type: A5 - Illegal Dump By: 67 ,Gray Name of Site: Comments: Put up post no dumping sign on pole located at westside of dock area.
Inspection: 2/23/2000 Time: PM 12:50 Type: A5A - Illegal Dump (State Open-Dump) By: 67 ,Gray Name of Site: Sang Wook RA Comments: Respondent caused or allowed accumulation of debris, rubbish, garbaage etc.
Inspection: 2/24/2000 Time: AM 11:00 Type: A5A - Illegal Dump (State Open-Dump) By: 67 ,Gray Name of Site: Sang Wook RA Comments: Owner respondent for removal nuisance violation penalty.
Inspection: 4/7/2000 Time: AM 08:10 Type: A5 - Illegal Dump By: 67 ,Gray Name of Site: Comments:

11200 S Edbrooke Ward: 09 Zipcode: 60628 Police: 05 LPC: 0316495123
Inspection: 11/16/2000 Time: PM 02:55 Type: A9 - Demo/NESHAPS By: 85 ,Kay Name of Site: Demo Site Comments: Demo no activity.
Inspection: 9/19/2001 Time: AM 11:15 Type: A8 - Site Assesment By: 67 ,Gray Name of Site: Comments: No illegal dumping
Inspection: 10/30/2001 Time: AM 10:49 Type: A5 - Illegal Dump By: 67 ,Gray Name of Site: Comments: No dumping found.
ENFORCEMENT
Enforcement Date: 1/29/2000 Enforcement Type:3DN - 3 Day Notice Company: Ra, Sang Wook Served: Sang Wook Ra Mail Address: 11200 S Edbrooke Chicago, II 60628 Issued By: , 1st Court Date: Last Court Date: Total Hearings: Disposition: - Fine: Comments:
TICKET DOCKET CHARGE DESCRIPTION LIABLE
Enforcement Date: 2/24/2000 Enforcement Type: ADM - Adminsitrative Hearings
Company: Ra, Sang Wook Served: Ra Sang Wook
Mail Address: 11200 S Edbrooke Chicago, II 60628 Issued By: 67 ,Gray 1st Court Date: 3/16/2000 Last Court Date: Total Hearings:
Disposition: AH VD - Fine: \$1,500.00 Comments:
TICKET DOCKET CHARGE DESCRIPTION LIABLE
405344 00-80177 7-28-450 Owner responsible for nuisance L
405344 00-80177 7-28-720 Accumlate junk atracting rats L

11200 S Edbrooke

COMPLIANTS: 1 INSPECTIO

INSPECTIONS:12 ENFORCEMENT:2

 11200-32 S Edbrooke
 Ward: 09 Zipcode: 60628 Police: 05 LPC: 0316495123

 COMPLAINTS INSPECTIONS

 Inspection: 3/11/1999
 Time: PM 02:25 Type: A9 - Demo/NESHAPS By: 68 ,Rodriguez

 Name of Site: Demo Site

 Comments: Demo in progress just starting barriers & safe guards being set up.

 Inspection: 11/20/2000

 Time: PM 03:15
 Type: A9 - Demo/NESHAPS By: 85 ,Kay

 Name of Site: Demo Site

 Comments: Demo in progress. Bldg. 100% down water tower removed.

ENFORCEMENT

11200-32 S Edbrooke

COMPLIANTS:0

0 INSPECTIONS: 2

ENFORCEMENT:0

Records for Neighboring Sites

		FREEDOM	JE INFO	RMATION	KEF	VORT		
11147 S Michigan	Ward: 09	Zipcode:	60628	Police:	05	LPC:		
COMPLAINTS INSPECTIONS								
Inspection: 8/5/1999 By: 67 ,Gray Comments: Grease on debris feft	/ ground arour	Name of S	Site: Ran	ich Steak H		e Ilowed the accumulation of	garbage	
Inspection: 8/26/1999 Time: PM 01:22 Type: A5 - Illegal Dump By: 67 , Gray Name of Site: Comments: Visual								
ENFORCEMENT								
Enforcement Date: 8/5/1999 Enforcement Type: ADM - Adminsitrative Hearings Company: Ranch Steack House Served: Eustache Venardos Mail Address: 11147 S Michigan Chicago, II 60628 Issued By: 67 ,Gray								
1st Court Date: 9/		Last Court I	Date:		Tota	l Hearings:		
Disposition: AH Comments: PD		ED	Fine: \$3	00.00				
TICKET	DOCKET	CHARGE			DESC	CRIPTION	LIABLE	

TICKET	DOCKET	CHARGE	DESCRIPTION	LIABLE
402145	99-80564	7-28-450	Owner responsible for nuisance	L
402145	99-80564	7-28-720	Accumlate junk atracting rats	L

11147 S Michigan

COMPLIANTS: 0

INSPECTIONS:2 ENFORCEMENT:1

THE FOLLOWING LIST ARE OLD BUILDING DEPARTMENT PERMITS ISSUED FOR UNDERGROUND STORAGE TANK WORK PRIOR TO 1/1/1993

ADDRESS	<u>11151 S M</u>	ICHIGAN LAST KNOWN SITE NAME: NEISNER DN	OS ST
DATE ISSUED	BUILDING PERMIT	COMMENTS	WORK BY
9/29/1954	119255	INSTALL 1-1K GAL FUEL OIL TANK FINAL 6/8/55	W & B TAUB COMPANY

THE FOLLOWING LIST ARE OLD BUILDING DEPARTMENT PERMITS ISSUED FOR UNDERGROUND STORAGE TANK WORK PRIOR TO 1/1/1993

ADDRESS	<u>11155 S M</u>	CHIGAN LAST KNOWN SITE NAME: THREE SI	STERS STORE
DATE ISSUED	BUILDING PERMIT	COMMENTS	WORK BY
9/23/1947	354729	INSTALL 1-1K GAL FUEL OIL TANK FINAL 9/26/47	WATER TUBE BOILER & TANK

11200 S Michigan COMPLAINTS INSPECTIONS	Ward: 09 Zipco	ode: 60628 Police:	05 LPC:	
Inspection: 10/18/1999 By: 67 ,Gray Comments:		e: A8 - Site Assesment e of Site:		
ENFORCEMENT 11200 S Michigan	COMPLIANT	S:0 INSPECTIONS:	1 ENFORCEMENT:0	

THE FOLLOWING LIST ARE OLD BUILDING DEPARTMENT PERMITS ISSUED FOR UNDERGROUND STORAGE TANK WORK PRIOR TO 1/1/1993

ADDRESS:	<u>11200 S M</u>	ICHIGAN LAST KNOWN SITE NAME: NATIONAL CL	OTHING
DATE ISSUED	BUILDING PERMIT	COMMENTS	WORK BY
8/12/1955	178046	INSTALL/ENCLOSE 1-1K GAL FUEL OIL TANK FINAL N/G	WATER TUBE BOILER & TANK

Underground Storage Tank FREEDOM OF INFORMATION AS OF Tuesday, October 20, 2009

FACILITY:	Kang Won H	Facility ID: 2036925	IEMA Number: 0
	11201 S MICHIGAN		
	CHICAGO, IL 60628 WARD: 09		
	CONTACT: MR WON H KANG PHONE:		
Owner:	UNKNOWN 1307 S WABASH		
	CHICAGO IL 60605		
	CONTACT: MR LEO FRONTERA PHONE: (312)	461-9600	

TANK		STATUS		SIZE	Material in Tank		Install Date	Date Tank Last Used	
PERMIT		TYPE			INSPECTED	CONTRACTOR & COMMENTS			
101042	ABANDC	N	06/24/1994		10/04/1994 🖟	SAFETY ENVIRONMENTAL CONSULTANTS TANK CAN NOT BE LOCATED.			
Comme	Comment Date Comments								
10/4/	(1994								

11211 S Eda	orooke	Ward: ()9 Z	ipcode:	60628	Police:	05	LPC:
	rs							
Recieved:	6/27/1997	AM 10:45	Taken	By: CJV	EScode:	09 - Juni	yard	
Site Name:	Residential	Area			Handled	IBy 21 R	ober	ts, George
Site Name: Ticket No:		Cour	t Date:					
Comments:	Cars being oil stained &	worked on				nge & dur	nped	in the back of the garage & alley. Ground is

INSPECTIONS

ENFORCEMENT

11211 S Edbrooke COMPLIANTS: 1 INSPECTIONS: 0 ENFORCEMENT: 0

11219 S Michigan Ward: 09	9 Zipcode:	60628 Police: 05 LPC:				
COMPLAINTS INSPECTIONS						
Inspection: 4/3/1998 Time: PM 01:01 Type: A10 - Building Recycling Program By: 56 ,Kelly Name of Site: Giant Beauty Supply Comments: For failure to establish an effective recylcing program in commercial establishments.						
Inspection: 10/13/1998 Time: PM 12:08 Type: A10 - Building Recycling Program By: 47 ,Walsh Name of Site: Giant Beauty Supply Comments: Company is in compliance. Observed dumpster for OCC 7 BBs for glass & cans.						
ENFORCEMENT						
Enforcement Date: 4/3/1998 Enforcement Date: 4/3/1998 Enforcement Succession Company: Giant Beauty Su Mail Address: 11219 S Michiga Issued By: 56 ,Kelly	apply Served:	_				
1st Court Date: 4/30/1998 Last Court Date: Total Hearings: 1.00						
Disposition: AH VC - CLOSED Fine: \$50.00 Comments:						
TICKET DOCKET	CHARGE	DESCRIPTION	LIABLE			
400147 9880072	11-5-023	Commercial Bldg recycling program				


11219 S Michigan

COMPLIANTS: 0

:0 INSPECTIONS:2

ENFORCEMENT:1

EnviroMapper for Envirofacts





City of Chicago **Richard M. Daley, Mayor**

Department of Environment

Suzanne Malec-McKenna Commissioner

2nd Floor 30 North LaSalle Street Chicago, Illinois 60602-2575 (312) 744-7606 (Voice) (312) 744-6451 (FAX) (312) 744-3586 (TTY)

http://www.cityofchicago.org

MEMORANDUM

то:	Richard Monocchio Commissioner Department of Buildings
FROM:	Suzanne Malec-McKenna Commissioner
RE:	Environmental Compliance Certification Code Enforcement and Demolition Program Building Deconstruction Work Program (1 Site)
DATE:	September 27, 2010

The Department of Environment (DOE) has completed the required federal environmental assessment review for the federally funded project listed below (the project), namely:

1. 11200 S. Edbrooke Ave.

DOE has determined that the project is in compliance with the environmental laws and authorities cited in the U.S. Department of Housing and Urban Development's (HUD's) "Environmental Review Procedures for Entities Assuming HUD Environmental Responsibilities," as set forth in 24 CFR Part 58.

Please note that this environmental clearance is conditional upon abating any asbestos containing materials (ACM), which may be present, in accordance with all local, state, and federal regulations.

In accordance with the federal grant conditions, DOE has prepared the applicable environmental review record file for the project. This record file documents the City's finding that the proposed project actions are part of a larger undertaking for which a Finding of No Significant Impact (FONSI) was made on April 6, 2009 and May 28, 2010, and for which circumstances have not changed significantly. All documentation supporting the FONSI level of clearance determination for this project will be maintained by DOE.

Should you have any questions regarding this matter, please contact Kevin M. Laberge, of my staff, at (312) 742-0463.

cc: James Harney, DOB Donald Mitchell, DOB Eileen Kramer, DOB Robert Wolf, DCD Rona Jeongco, DCD Katie Ludwig, DCD Meghann Moses, Chicago Workforce Investment Council



SMM UMBR kml





ത

MEMORANDUM

То:	Michael Merchant Commissioner Department of Buildings
From:	David J. Reynolds, P.E., LEED AP
Date:	April 23, 2012
Subject:	Environmental Compliance Certification Code Enforcement and Demolition Program (1 Site

The Department of Fleet and Facility Management (2FM) has completed the required federal environmental assessment review for the federally funded projects listed below (the projects), namely:

1. 11200 S. Edbrooke Ave./11227 S. Michigan Ave.

2FM has determined that the projects are in compliance with the environmental laws and authorities cited in the U.S. Department of Housing and Urban Development's (HUD's) "Environmental Review Procedures for Entities Assuming HUD Environmental Responsibilities," as set forth in 24 CFR Part 58.

Please note that this environmental clearance is conditional upon abating any asbestos containing materials (ACM), which may be present, in accordance with all local, state, and federal regulations.

In accordance with the federal grant conditions, 2FM has prepared the applicable environmental review record file for the projects. This record file documents the City's finding that the proposed project actions are part of a larger undertaking for which a Finding of No Significant Impact (FONSI) was made on May 28, 2010, and for which circumstances have not changed significantly. All documentation supporting the FONSI level of clearance determination for these projects will be maintained by 2FM.

If you have any questions regarding this matter, please contact Kevin M. Laberge, of my staff, at (312) 742-0463.

cc: James Harney, DOB Don Mitchell, DOB Eileen Kramer, DOB Kimberly Worthington, 2FM

DJR/EHSM/kml

				r			
Area of statutory or regulatory compliance	Not applicable to this project	Consultation required	Review required	Permits required	Determination of consistency (approvals, permits obtained)	Conditions and/or mitigation actions required	Provide compliance documentation. Additional material may be attached.
Historic properties					~		Check of SHPO Review, Illinois State Historic Structures Survey, Chicago Landmarks Commission, assessment of photos of the project. Received approval from DHED Historic Preservation Division.
Floodplain				———			Check of FEMA Floodplain Maps. Project is not located in
management					✓		a floodplain - Map Number 17031C0655J.
Wetlands protection					~		Check of the Designated Wetlands Area Review, USGS 7.5 Minute Maps.
Coastal zone	~						The City of Chicago is in an Inactive State (Coastal Zone
management	Ý						Management Program).
Water quality, aquifers	1						The City of Chicago is not within an Aquifer Recharge Zone (USEPA). Potable water supply from wells are prohibited from being used or installed in the City of Chicago (MOU between the City of Chicago and the IEPA).
Endangered species	~						The project will not have an impact on any endangered species (US Fish and Wildlife information).
Wild and scenic rivers	~						The project will not have an impact on classified Wild and Scenic Rivers.
Air quality	~						The City of Chicago is classified as non-attainment for ozone. The project will not have an impact on air quality.
Farmland protection	\checkmark						The project area is already committed to urban use.
Manmade hazards:					1		
Thermal/explosive					~		The project has an acceptable separation distance from any facility storing flammable and explosive material. Source: DOE Fileroom.
Noise					~		The project is not within 1000 feet of a 4 or more lane highway or 15 miles of an airport The project is within 3000 feet of a railroad; however, a noise assessment indicated a an acceptable final DNL of 51.2 dB (Noise assessment guidelines).
Airport clear zones					~		The project is not within 5 miles of a civil airport or 15 miles of a military airport.
Toxic sites					~		Check of EPA Superfund National Priorities List, CERLIS sites list, Agency for Toxic Substances and Disease Registry information, Phase I ESA.
Environmental justice	\checkmark						Executive Order No. 12898. Review of current literature.
Flood insurance, § 58.6 (a)	~						Check of Flood Insurance Rate Maps (FEMA), Proof of requisite flood insurance.
Coastal barriers, § 58.6 (b)	~						The City of Chicago is an inland city; not affected.

State or local statutes: Nothing to add.

Prepared by: Kevin M. Laberge, P.E.Kevin M. Laberge

Statutory Checklist for NEPA	Environmental Review - Federal Laws and	Authorities Listed at § 58.5

Statutory Checklist for NEPA Environmental Review - Federal Laws and Authorities Listed at § 58.5									
· 1/- 2 2-	Date: 04/23/12								
Signature									




Environmental Review of Vacant Buildings For Proposed Demolition

Inspected By	Louis BRA	m E	
Date Inspected	2-6-12		
Property Address(es)		11 1 11000 0	mili
	11200 S. E.	dbrooke/11227 S	. Michigan
Property Identification Number(s) (PINS)			
	25-22-107-0	52	
Community Area (if known)			
	YES	NO	
Occupied		L	
Vacant			
Is it habitable?	A	<u> </u>	
Percentage of Deterioration	14% E	ot. DNU	
Number of Units	/ N	on Res.	
Detailed Scope of Work	D 1-1-	-/	
Describe, in detail, the project actions that will	Demolition	ser city	
occur at the project location. Also, explain why	1 count H	1000	
these activities are being pursued in lieu of	Acquir, Ce	by chunch	
alternatives. Site photographs should also be	R 1/2	0	
included.	Bundang .		
Reviewed By (Supervisor Name)	1 Jan		
Date Submitted to Department of Environment	3-14-1.	2	
Please ensure the following is included with all fo			
1. Building inspection report, photos, findings, a			
		1	
 Demolition order, if available; N/A City Evidence that attempts are made to provide 	relocation services for cur	rent tenants; NA	
4. Source of funding and approximate costs for	demolition \$750,000	, e.s // ·	
5. Any other details that could be relevant to th	e project (property transa	ction screen reports;	
historic use information; environmental reports,	etc.).		
, , ,			
To be completed by Department of Environment	nent		
	Date Reviewed:		
Clearance Granted:			
Clearance Denied:			

Page 1 of 1

V This is she play.



25221070320000 07/23/2007

Cook County Page assumants



CITY OF CHICAGO Department of Buildings CHECKLIST Inspection Report

CONTROL NUMBER ANNUAL 120145682 10539707 SURVEY								-	COMPLAINT OTHER Case#. 322357 VBR#:													
	12 C.A.	14	СТ	16 DATE	OF B		<u>' </u>		4 NUMBER DIR 32 LOCATION OF PREMISES							F/R						
UE									1200 S EDBROOKE AVE CATION OF PREMISES								F/R					
OK 11 OWNER'S NAME									35 ADDRESS 59 CITY AND STATE								75 76					
02	02																		м			
03	11 AGENT'S NAME 03									35 ADDRESS 59 CITY AND STATE							_	75				
04	11 LESSEE OR CONTRACT PURCHASER									35 ADDRESS 59 CITY AND STATE							75	U				
05									BLDG U 33 STYS IS THERE A GARAGE VACANT AND G GARAGE? N OPEN?						GAR	RAGE TYPE						
06	35 SIZE OF 38 BUILDING 42 FLOOR AR							REA	49 TOTAL BLDG A 56 BUILDING AREA M FEE GARAGE DEMO							EMO ES	STIMA	ΓE				
	11 TYPE C	F CO						33 CL	ASS CL	49	BAS	EMENT		-LOFT	NO.	OF ST	ORIES	RIES BLDG. VAC			. & OPEN	
07	ORDINAR							3B				NO		NO		5			NO		_	
08	11 OCCUP STORAGE			SIFICATI	ON			33 CL H	ASS CL	48-60	-	1DTH 75		NGTH 65	TH HEIGHT BI				568750			
09	CONVE	RTED	IF (CONVER	TED,	DESCR	BE O		AL USE			10 1					and the second s	SENT N	ENT NUMBER.			
05	NON	-RES			S	1	NUME		PTS.	1		EMO E	STIMAT	E		PA	RTY W	ALL PW2				
10			1		-		_	0					2444-047		K		NO			NO OF		
11	INSPECTION # VIOLATION NUMBER																					
CN193110								ES														
			_					ELE	ELECTRICAL - COMED SVC TERMINATED AT POLE													
									GLAZING - BROKEN OR MISSING													
									MASONRY - DANGEROUS AND HAZARDOUS MASONRY - LOOSE OR MISSING BRICK													
									MASONRY - MISSING SECTIONS													
									MASONRY - STEP OR STRESS FRACTURES													
									MASONRY - WASHED OUT MORTAR JOINTS													
		_	the second s	IORATIO	_				MASONRY - LOOSE AND FALLING BRICKS FRONT AND REAR ELEVATIONS. FRONT SASH - BROKEN, MISSING OR INOPERABLE													
<u> </u>	LECTRICA							%														
P P	LUMBING (_			IPING	-FIXT		9%														
\vdash					CLUD			%														
MASONRY (FDN. & CHIMNEY INCLUDED) 8% ROOF COVERING & SHEATHING 0%																						
RAFTERS 0%																						
CPNTRY, FLOORS 0%							%															
JOISTS 0%							1%															
STUDDING & PARTITIONS 0%							196															
WALLS-FRAME CONST. %							%															
SASH-FRAMES-DOORS-TRIM 3%							1%															
STAIRS & PORCHES (INT. & EXT.) 0%																						
PLASTER 0%																						
						%		0.0.41			_	2010	0.110						1			
							SPEAT	GOAL:	ICOT!	ידסטיי	NUMBE	BOAR		0810	SIGNA		EMOLITI	NU				
RECOMMENDED T B							SPECTIC 2:24:01P		ISPEL	BL006								1	-			
					RE				DATE: CHIEF'S SIGNATURE					ATE:								
VBR Plector Inveliese												3/14/ 20)12									
TIT	LE SEARCI	HOR	DERED									DATE	1	1								



Date: 2/6/2012 12:24 PM Description:



Date: 2/6/2012 12:24 PM **Description:**



Date: 2/6/2012 12:24 PM Description:



Date: 2/6/2012 12:24 PM **Description:**







Date: 2/6/2012 12:24 PM Description:



Date: 2/6/2012 12:24 PM **Description:**



Date: 2/6/2012 12:24 PM **Description:**





Date: 2/6/2012 12:24 PM **Description:**



Date: 2/6/2012 12:24 PM **Description:**



Date: 2/6/2012 12:24 PM Description:

Date: 2/6/2012 12:24 PM **Description:**



Date: 2/6/2012 12:24 PM Description:



Date: 2/6/2012 12:24 PM **Description:**





Date: 2/6/2012 12:24 PM Description:



Date: 2/6/2012 12:24 PM Description:






Date: 2/6/2012 12:24 PM **Description:**




<u>اھ</u>

*



25221070320000 07/23/2007

Close Windov



Information provided on the City of Chicago web site should not be used as a substitute for legal, accounting, real estate, business, tax, or other professional advice. The City of Chicago assumes no liability for any damages or loss of any kind that might arise from the use of, misuse of, or the inability to use the City web site and-or the materials contained on the web site. The City of Chicago also assumes no liability for any damages or loss of any kind that might arise from the use of, misuse of, or the inability to use the City web site and-or the materials contained on the web site. The City of Chicago also assumes no liability for improper or incorrect use of materials or information contained on its web site. All materials that appear on the City of Chicago web site are distributed and transmitted as is, without warranties of any kind, either express or implied, and subject to the terms and conditions stated in this disclaimer.

ø

ZONE Class B1-3	ification	Ordinance Number		Ordina	nce Date	
TIF Roseland/Michie	gan					
Building Id 841444		ir Street Type Stories MICHIGAN AVE	Units	Built Sq.Ft.	Conditio	n Vacancy
Map Index 28-E		Page Number 226B	x			
PIN 2522107032	From Address	To Address	Dir S	Street MICHIGAN	Type AVE	Suffix
Lot Number 2	-					
Ward 9	Alderman ANTHONY BEALE	Phone 773-785-1100		Address 34 East 112th	Place	

Close Window

City of Chicago, Code Enforcement and Demolition Program (DOB) Sec-106 Review – Historic Property Identification Checklist

HED Form 5/21/10

Property ac	ldre	ss:		11	200 S. Edbrooke / 11227 S. Mic	higan	
Instructions:	(1)	Att	ach:		Current photos of property (front and rear ele properties, both street elevations and rear ele On-line Chicago Zoning Map for property (cu http://maps.cityafchicago.org/website/zoning, HAARGIS Map/Report (color PDF) and (if a Information Report at http://www.illinoishista	evation) olor PDF) (<u>/index.html</u> pplicable) (at Property
	(2) (3) (4)	Aft	er H	te Par. ED rev for file.	A and email to HED/Historic Preservation D iew. complete identified additional steps (Part	Vivision with B below) of the and Part w/IHPA con (), copies of c	h attachments as applicable A below acturrence iny other
PART A	\boxtimes	No		Yes	A.1. Is property a National Historic Landmar	'k (NHL)?	··
		No		Yes	A.2. Listed (or determined eligible) for Nation Indiv:	nal Registe	er of Historic Places?
		No		Yes	Distrt: A.3. A Chicago Landmark or in a Chicago La Indiv:	andmark D	istrict?
	\boxtimes	No		Yes	Distrt: A.4. Color-coded red or orange in Chicago H	listoric Res	ources Survey?
		No		Yes	Attach: Copy of Detail Report (use "Search <u>http://egov.citvofchicago.org/Landn</u> A.5. Identified in HAARGIS? HAARGIS was unavailable. IHPA staff ad completed without it, per an email dated 1/	<u>narks/CHRS</u> lvised that	.html
	Opt	tional:	If 'Y	es' to	A.I, A.2 or A.3 above:	× ()? 2 200	
		Atta livi	nch cu ng ro	orrent ons/p	interior photos of property (e.g., front entry ves arlors. dining rooms, other rooms with intact h 1 areas in multi-unit buildings, etc.)	tibule, entr istoric feat	ry hall, stair halls, ures. hallways and
	Cor	mpleted			Terry Tatum, HED	Date:	4/17/12

PART B (to be completed by HED/Historic Preservation Division)

Pursuant to NSP Programmatic Exemption:


- Property is not a historic property for the purposes of Sec-106 Review. Review process is complete.
- □ Property is □ listed, □ determined eligible. □ certified (i.e., in a local district), or □ appears to be eligible for listing on the National Register, either □ individually and/or as □ a contributing building to a district. Submit this checklist with a transmittal memo and all attachments to IHPA.

The following interior rooms and spaces should be identified as character-defining features:

Submit this form, all attac	hments, and HED opinion memo to IHPA for co	oncurrenc	e	
Property does not appea	r to be eligible for listing on the National Register.	either ind	lividually or as	a
contributing building to	a district.		•	
Other:	TT			
Completed by (signature):	-in fort	Date:	4/17/12	

Typed name/title:

Terry Tatum Coordinating Planner I



NEPA Environmental Review Record: 11200 S EDBROOKE AVE

SUMMARY OF TRAFFIC COUNTS (Buffer= 1000 ft)

LOCATION	DATE COUNTED	TRAFFIC COUNT	DISTANCE (ft)
No records			
found.			

SURROUNDING ARTERIAL STREETS (Buffer= 1000 ft)

STREET NAME	DISTANCE
MICHIGAN	355
111TH	695
STATE	908

SUMMARY OF AIRPORT GEOGRAPHIES

Does the property fall within a Non-Central Runway Protection	
Zone?	N
Does the property fall within a Central Runway Protection Zone?	N
Does the property fall within 65 DNL Noise Contours?	N

SUMMARY OF RAILROADS (Buffer= 3000 ft)

RAIL TYPE	SERVICE LINE	DISTANCE (ft)	NEAREST STATION	PER DAY FREQUENCY	OVERNIGHT FRACTION	GIS ID	
		111th Street	91	0.13			
Commuter	METRA-Electric, S. Shore	2412.86	Kensington (115th Street)	125	0.22	118	

FREIGHT LINES EXIST=YES

SUMMARY OF LANDMARK DESIGNATIONS (Buffer= 250 ft)

Site	National Register	Landmark District	Landmark	CHRS Color
No records found.				

SUMMARY OF FILE ROOM (Buffer= 650 ft)

Address	Complaint	Inspection	Enforcement	P2	Demo_Permit	UST_New	UST_Bldg	Installation	AST	Distance
11200 S Edbrooke	Y	Y	Y	N	N	N	N	N	N	31.4
11200-32 S										
Edbrooke	N	Y	<u>N</u>	N	Y	N	<u>N</u>	N	N	31.4
11211 S Edbrooke	Y	N	N	N	N	N	N	_N	N	114.17
11153 S Edbrooke	N	N	N	N	Y	N	N	N	<u>N</u>	
11221 S Edbrooke	N	N	N	N	Y	N	N	N	N	211.22
11223 S Edbrooke	N	Y	N	N	Y	N	N	N	N	231.41
11201 S Michigan	N	N	N	N	N	Y	N	N	N	316.27
11155 S Michigan	N	N	N	N	N	N	Y	N	N	319.66
11151 S Michigan	N	N	N	N	N	N	Y	N	N	331.04
11147 S Michigan	N	Y	Y	N	N	N	N	N	N	348.79
11219 S Michigan	N	Y	Y	N	N	N	N	N	N	371.73
11236 S Edbrooke	N	N	N	N	Y	N	N	N	N	378.44
11148 S Indiana	N	Y	N	N	Y	N	N	N	N	391.8
11200 S Michigan	N	Y	N	N		N	Y	N	N	396
11210 S Michigan	N	 N	N	N	N	N	N	Y	N	406.74
11218 S Indiana	N	N	N	N	N	N	N	Y	N	409.47
11218-24 S										
Michigan	N	N	N	N	N	N	Y	N	N	441.68
11226 S Indiana	Y	Y	N	N	N	N	N	N	N	455.72
11120 S Edbrooke	N	N	N	N	Y	N	N	N	N	459.03

City of Chicago Department of Environment

Address	Complaint	Inspection	Enforcement	P2	Demo_Permit	UST_New	UST_Bldg	Installation	AST	Distance)
11140-42 S	T T						e 6	2		
Michigan	N	N	N	N	N	N	N	N	Y	472.17
11224 S Michigan	N	N	N	N	N	N	N	Y	N	480.5
11232 S Michigan	N	Y	Y	N	N	N	N	N	N	496.68
11247 S Edbrooke	N	N	N	N	Y	N	N	N	N	497.39
11117 S Edbrooke	N	Y	N	N	Y	N	N	N	N	510.17
11121 S Michigan	N	N	N	N	N	N	N	Y	N	540.07
11120-22 S										
Michigan	N	N	N	N	Υ	N	N	N	N	573.19
11117 S Michigan	N	N	N	N	Y	N	N	N	N	579.71
11242 S Michigan	N	N	N	N	N	N	N	Y	N	582.24
34 E 112TH PL	N	Y	N	N	N	N	N	N	N	599.64
11116 S Michigan	N	Y	N	N	Y	N	N	N	N	614.61
11114-16 S										
Michigan	N	N	N	<u>N</u>	Y	N	N	N	N	634.74
33 E 112TH PL	N	N	N	N	Υ	N	N	<u>N</u>	N	637.99
Total=32										



The attached pages contain FOIA search results for the following addresses:

11140 to 11236 S EDBROOKE AVE

Results Summary

Item	Current System*	Old System*
Permits		NA
Inspections		X
Complaints		Х
Enforcement		х
Tank Assets		
AST	Included in Tank Assets	
Air Equipment	-	See Current System
Asbestos		х
LUST NFR**		NA

* The Current System contains information after 4thQ 2011. Records prior to 4thQ 2011 are generally found in the the Old System.

** CDPH only maintains NFR Letters from LUST cleanups. Records for SRP and all other NFRs can be obtained from the Chicago Department of Fleet and Facilities Management.

X - Records found.



Environmental Inspections From Old Database

11200-11200 S EDBROOKE

Inspection Date	Site Name	Inspection Type	Comments
2001-10-30		A5	No dumping found.
2001-09-19		A8	No illegal dumping
2000-11-16	Demo Site	A9	Demo no activity.
2000-07-04		A5	
2000-02-24	Sang Wook RA	A5A	Owner respondent for removal nuisance violation penalty.
2000-02-23	Sang Wook RA	A5A	Respondent caused or allowed accumulation of debris, rubbish, garbaage etc.
2000-01-20		A5	Put up post no dumping sign on pole located at westside of dock area.
1999-12-20		A5	Drop off posted sign
1999-11-15		A5	
1999-10-12	Sang Wook RA	A5A	Approx 40-45 cu yds of waste material. Waiting for litle search of property owner to continue further action & clean up.
1999-04-11		A5	
1999-01-12		A5	Found site to have apprx 40 - 50 cu yds of dumped waste material. Waiting for litle search of peroperly owner.

11200-11232 S EDBROOKE

Inspection Date	Site Namo	Inspection Type	Comments
2000-11-20	Demo Site	A9	Demo in progress. Bldg. 100% down water tower removed.
1999-11-03	Demo Site	A9	Demo in progress just starting barriers & safe guards being set up.



Environmental Inspections From Old Database

11223-11223 S EDBROOKE

Inspection Date	Site Name	Inspection Type	Comments
2010-09-27	Demo Site	A9	A demolition inspection was conducted at the above address. At the time of the investigation I saw that the structure had been 100% demolished and the site graded.\nSee the attached checklists for further information.\nNo activity was observed while on site. The property at this time was owned by the city of Chicago\n

Inspection Type	Description
A5	Illegal Dump
A5A	Illegal Dump (State Open-Dump)
A8	Site Assesment
A9	Demo/NESHAPS



Environmental Complaints From Old Database

11200-11200 S EDBROOKE

Date Received	Facility	Code	Comments
12/7/99	Sang Wook RA	15	Fly dumping of tires & debris at the above loc. Garbage clothing, cardboard, boxes, & two tires dumped in open space dock in area.

11211-11211 S EDBROOKE

Date Received	Facility	Code	Comments
6/27/97	Residential Area	9	Cars being worked on and motor oil is being change & dumped in the back of the garage & alley, Ground is oil stained & auto repair has taken place.



Environmental Code Enforcement From Old Database

11200-11200 S Edbrooke

Date	Company	Liable	Туре	Charge	Comments
2/24/00	Ra, Sang Wook	L	ADM	7-28-450 : Owner responsible for nuisance	
2/24/00	Ra, Sang Wook	L	ADM	7-28-720 : Accumlate junk atracting rats	



Asbestos Notifications From Old Database

11153 S EDBROOKE

Notification Type: DEMO NOTICE OF INTENT

Notification Date: 1996-03-27

Owner City of Chicago		Contractor ID UN01		Begin Date 1996-03-29	Complete Date 1996-05-23	
RACM Volume (CF)	RACM Pipe (FT)	Estimated Waste (CY)	Waste	Hauler	Disposal Site	
0		145 cu yds.	CID	andfill	138th & Calumet	
=t) Le	ength (Ft)	Width (Ft)	Î.			
	50	22				
		Comme	ents	1.21-	2 ×	
	City of Chi RACM Volume (CF) 0	City of Chicago RACM Volume (CF) 0 Et) Length (Ft)	City of Chicago UNI RACM Volume (CF) RACM Pipe (FT) Estimated Waste (CY) 0 145 cu yds. Et) Length (Ft) Width (Ft) 50 22	City of Chicago UN01 RACM RACM Estimated Volume Pipe (FT) Waste (CY) 0 145 cu yds. CID 1 Et) Length (Ft) Width (Ft)	City of Chicago UN01 1996-03-29 RACM Volume (CF) RACM Pipe (FT) Estimated Waste (CY) Waste Hauler 0 145 cu yds. CID Landfill =t) Length (Ft) Width (Ft) 50 22	



Asbestos Notifications From Old Database

11200 S EDBROOKE

Notification Type: DEMO NOTICE OF INTENT

Notification Date: 1999-02-26

Owner				Begin Date	Complete Date
City of Chi	cago	NAC	01	1999-03-10	
RACM RACM Estimated W Volume Pipe (FT) Waste (CY) W		Waste	Hauler	Disposal Site	
0		80 cu yds.	Land &	& Lakes	2000 E. 122nd St.
t) Le	ength (Ft)	Width (Ft)			
	204	160			
1		Comme	nts		
	City of Chi RACM Volume (GF) 0	City of Chicago RACM RACM Volume Pipe (FT) 0 t) Length (Ft)	City of Chicago NAC RACM Volume (GF) RACM Pipe (FT) Estimated Waste (CY) 0 80 cu yds. t) Length (Ft) Width (Ft) 204 160	City of Chicago NA01 RACM RACM Estimated Volume Pipe (FT) Waste (CY) 0 80 cu yds. Land d t) Length (Ft) Width (Ft)	City of Chicago NA01 1999-03-10 RACM Volume (GF) RACM Pipe (FT) Estimated Waste (CY) Waste Hauler 0 80 cu yds. Land & Lakes t) Length (Ft) Width (Ft) 204 160

Notification Date: 2000-11-09

Owner			Contrac	tor ID	Begin Date	Complete Date
City of Chicago		MIQ	01	2000-11-10	2000-11-20	
RACM Area (SF)	RACM Volume (CF)	RACM Pipe (FT)	Estimated Waste Hauler Dispo		Disposal Site	
0	0	0				Loop/2401 S. Laflin
Height (Ft) Le	ength (Ft)	Width (Ft)			
20		15	15			
and the second			Commo	ints	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	



Asbestos Notifications From Old Database

11221 S EDBROOKE

Notification Type: DEMO NOTICE OF INTENT

Notification Date: 1996-08-13

Owner			Contractor ID AC01		Begin Date	Complete Date
City of Chicago		1996-08-13				
RACM Area (SF)	RACM Volume (CF)	RACM Pipe (FT)	Estimated Waste (CY)	Waste Hauler		Disposal Site
	0		75 cu yds.	Tri-State	e Landfill	Lynwood, IL
Height (I	Ft)	ength (Ft)	Width (Ft)			
20		45	30			
	1000	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Comm	ents		



Asbestos Notifications From Old Database

11223 S EDBROOKE

Notification Type: DEMO NOTICE OF INTENT

Notification Date: 2010-08-05

Owner City of Chicago			Contractor ID		Begin Date 2010-08-05	Complete Date
RACM Area (SF)	RACM Volume (CF)	RACM Pipe (FT)	Estimated Waste (CY)	Waste	Hauler	Disposal Site
0	0	0				- 14 A A A
Height (Ft) Le	ength (Ft)	Width (Ft)	Í		
0		0	0			
1.3.00			Comme	nts		-



Asbestos Notifications From Old Database

11236 S EDBROOKE

Notification Type: DEMO NOTICE OF INTENT

Notification Date: 1998-01-09

Owner			Contractor ID		Begin Date	Complete Date
City of Chicago			DE03		1998-01-12	
RACM Area (SF)	RACM Volume (CF)	RACM Pipe (FT)	Estimated Waste (CY)	Waste Hauler		Disposal Site
	0		150 yds.	CID	.andfill	138th & Calumet
Height (I	Ft) Le	ength (Ft)	Width (Ft)	0		
15		50	20			
1.1			Comme	ents		A CONTRACTOR



LUST NFR *

* CDPH only maintains NFR Letters for LUST cleanups. Records for SRP and all other NFRs can be obtained from the Chicago Department of Fleet and Facilities Management.



The attached pages contain FOIA search results for the following addresses:

11147 to 11219 S MICHIGAN AVE

Results Summary

Item	Current System*	Old System*
Permits		NA
Inspections		х
Complaints		
Enforcement		х
Tank Assets		X
AST	Included in Tank Assets	
Air Equipment		See Current System
Asbestos		
LUST NFR**		NA

* The Current System contains information after 4thQ 2011. Records prior to 4thQ 2011 are generally found in the the Old System.

** CDPH only maintains NFR Letters from LUST cleanups. Records for SRP and all other NFRs can be obtained from the Chicago Department of Fleet and Facilities Management.

X - Records found.



Environmental Inspections From Old Database

11147-11147 S MICHIGAN

Inspection Date	Site Name	Inspection Type	Comments
1999-08-26		A5	Visual
1999-05-08	Ranch Steak House	A5	Grease on ground around grease trap. Respondent caused or allowed the accumulation of garbage debris fefused.

11200-11200 S MICHIGAN

Site Name	Inspection Type	Comments
	A8	
	Site Name	Site Name Type

11219-11219 S MICHIGAN

Inspection Date	Site Name	Inspection Type	Comments
1998-10-13	Giant Beauty Supply	A10	Company is in compliance. Observed dumpster for OCC 7 BBs for glass & cans.
1998-03-04	Giant Beauty Supply	A10	For failure to establish an effective recylcing program in commercial establishments.

Inspection Type	Description			
A10	Building Recycling Program			
A5	Illegal Dump			
A8	Site Assesment			



Environmental Code Enforcement From Old Database

11147-11147 S Michigan

Date	Company	Liable	Туре	Charge	Comments
8/5/99	Ranch Steack House	L	ADM	7-28-450 : Owner responsible for nuisance	PD 9/16/99
8/5/99	Ranch Steack House	L	ADM	7-28-720 : Accumlate junk atracting rats	PD 9/16/99

11219-11219 S Michigan

Date	Company	Liable	Туре	Gharge	Comments
4/3/98	Giant Beauty Supply	1	ADM	11-5-023 : Commercial Bldg recycling program	



Tank Asset Information

Facility ID: 2036925

Company	Fullname	Capacity	Facility Phone
UNKNOWN	MR WON H KANG	Primary	

Facility ID Key

Facility ID	Address
2036925	11201 S MICHIGAN AVE



Pre-1992 USTs from Building Department

11151-11151 S MICHIGAN

Date Of Tank	Facility Name	Work By	Comments
1954-09-29	NEISNER DNOS ST	W & B TAUB COMPANY	INSTALL 1-1K GAL FUEL OIL TANK FINAL 6/8/55

11155-11155 S MICHIGAN

Date Of Tank	Facility Name	Work By	Comments
1947-09-23	THREE SISTERS	WATER TUBE	INSTALL 1-1K GAL FUEL OIL TANK
	STORE	BOILER & TANK	FINAL 9/26/47

11200-11200 S MICHIGAN

Date Of Tank	Facility Name	Work By	Comments
1955-08-12	NATIONAL CLOTHING	WATER TUBE BOILER & TANK	INSTALL/ENCLOSE 1-1K GAL FUEL OIL TANK FINAL N/G

11218-11224 S MICHIGAN

Date Of Tank	Facility Name	Work By	Comments	
1950-02-09	J. C. PENNEY COMPANY	SUMNER S. SOLLITT & COMPANY	INSTALL 1-15K GAL FUEL OIL TANK FINAL 10/13/50	




UST Permit Information From Old Database

FACILITY ID: 2036925


Permit Number	Permit Type	Issued Date	Completion Date	# Tanks	Permit Location	Comments
101042	ABANDON	6/24/94				LOCATED.
DATE				COMMEN	NTS	Sale In the set
10/4/94			OCATED. INSTI		ABOVE GRO	UND STORAGE

FACILITY ID KEY

Facility ID	Address	
2036925	11201 S MICHIGAN AVE	



= Subject Property




Map Type: Fire Insurance Publisher: Sanborn-Perris Map Co. Publication Name: Insurance Maps of Chicago, Illinois Volume E Base Map Date: 1897 Revised Date: Republished Date: Sheet Number: 0028

•






Leaflet




Map Type: Fire Insurance Publisher: Sanborn-Perris Map Co. Publication Name: Insurance Maps of Chicago, Illinois Volume E Base Map Date: 1897 Revised Date: Republished Date: Sheet Number: 0027






Map Type: Fire Insurance Publisher: Sanborn Map Co. Publication Name: Insurance Maps of Chicago, Illinois Volume G Base Map Date: 1911 Revised Date: Republished Date: Sheet Number: 0034


•







Map Type: Fire Insurance Publisher: Sanborn Map Co. Publication Name: Insurance Maps of Chicago, Illinois Volume G Base Map Date: 1911 Revised Date: Republished Date: Sheet Number: 0033

•





Map Type: Fire Insurance Publisher: Sanborn Map Co. Publication Name: Insurance Maps of Chicago, Illinois Volume 42 Base Map Date: 1939 Revised Date: Republished Date: Sheet Number: 4206




Map Type: Fire Insurance Publisher: Sanborn Map Co. Publication Name: Insurance Maps of Chicago, Illinois Volume 42 Base Map Date: 1939 Revised Date: Republished Date: Sheet Number: 4205



Map Type: Fire Insurance Publisher: Sanborn Map Co. Publication Name: Insurance Maps of Chicago, Illinois Volume 42 Base Map Date: 1939 Revised Date: March 1950 Republished Date: Sheet Number: 4206 .








Leaflet

Map Type: Fire Insurance Publisher: Sanborn Map Co. Publication Name: Insurance Maps of Chicago, Illinois Volume 42 Base Map Date: 1939 Revised Date: March 1950 Republished Date: Sheet Number: 4205 •







The attached pages contain FOIA search results for the following addresses:

33 to 145 E 112TH PL

33 to 145 E 112TH ST

Results Summary

ltem	Current System*	Old System*
Permits		NA
Inspections		Х
Complaints	Х	
Enforcement		
Tank Assets		
AST	Included in Tank Assets	
Air Equipment		See Current System
Asbestos		Х
LUST NFR**		NA
Highway Authority		

* The Current System contains information after 4thQ 2011. Records prior to 4thQ 2011 are generally found in the the Old System.

** CDPH only maintains NFR Letters from LUST cleanups. Records for SRP and all other NFRs can be obtained from the Chicago Department of Fleet and Facilities Management.

X - Records found.



Environmental Inspections From Old Database

34 E 112TH PL

Inspection Date	Site Name	Inspection Type	Comments
2011-06-02		A8	Drop off flyers
2005-11-04		A8	
2005-09-13		М	11th Ward Office.
2001-10-12		A8	Ald Office



Environmental Complaints

143 E 112TH ST

Date of	Complaint	Resolution	Inspector Comments
	SR# 12-01985640	UNF	called to question complainant no answer will try gain no access no location of complaint



Asbestos Notifications From Old Database

33 E 112TH

Notification Type: DEMO NOTICE OF INTENT

Notification Date: 12/17/2001





The attached pages contain FOIA search results for the following addresses:

11144 to 11238 S EDBROOKE AVE

Results Summary

ltem	Current System*	Old System*
Permits		NA
Inspections		Х
Complaints	х	Х
Enforcement		Х
Tank Assets		
AST	Included in Tank Assets	
Air Equipment		See Current System
Asbestos		х
LUST NFR**		NA
Highway Authority		

* The Current System contains information after 4thQ 2011. Records prior to 4thQ 2011 are generally found in the the Old System.

** CDPH only maintains NFR Letters from LUST cleanups. Records for SRP and all other NFRs can be obtained from the Chicago Department of Fleet and Facilities Management.

X - Records found.



Environmental Inspections From Old Database

Inspection Date	Site Name	Inspection Type	Comments
2001-10-30		A5	No dumping found.
2001-09-19		A8	No illegal dumping
2000-11-20	Demo Site	A9	Demo in progress. Bldg. 100% down water tower removed.
2000-11-16	Demo Site	A9	Demo no activity.
2000-04-07		A5	
2000-02-24	Sang Wook RA	A5A	Owner respondent for removal nuisance violation penalty.
2000-02-23	Sang Wook RA	A5A	Respondent caused or allowed accumulation of debris, rubbish, garbaage etc.
2000-01-20		A5	Put up post no dumping sign on pole located at westside of dock area.
1999-12-20		A5	Drop off posted sign
1999-12-10	Sang Wook RA	A5A	Approx 40-45 cu yds of waste material. Waiting for title search of property owner to continue further action & clean up.
1999-12-01		A5	Found site to have apprx 40 - 50 cu yds of dumped waste material. Waiting for title search of peroperly owner.
1999-11-15		A5	
1999-11-04		A5	
1999-03-11	Demo Site	A9	Demo in progress just starting barriers & safe guards being set up.



Environmental Inspections From Old Database

Inspection Date	Site Name	Inspection Type	Comments
			A demolition inspection was conducted at the above address. At the time of the investigation I saw that the structure had been 100% demolished and the site graded.
2010-09-27	Demo Site	A9	See the attached checklists for further information.
			No activity was observed while on site. The property at this time was owned by the city of Chicago

Inspection Type	Description
A5A	Illegal Dump (State Open-Dump)



Environmental Complaints

11200 S EDBROOKE AVE

Date of	Complaint	Resolution	Inspector Comments
5/3/12	SR# 12-00849992	INVALD	I responded to a dust complaint at the above location. Upon arrival, I observed a commercial building currently being demolished. I then spoke with Mr. Ocosta of NF Demolition and explained to him the reason for my visit. NF Demolition had a demolition pemit for the apparrent demolition. A water source was seen and the site was fenced and screened. No dust was observed at this time.

Date of	Complaint	Resolution	Inspector Comments
5/3/12	SR# 12-00849888	INVALD	I responded to a dust complaint at the above location. Upon arrival, I observed a commercial building currently being demolished. I then spoke with Mr. Ocosta of NF Demolition and explained to him the reason for my visit. NF Demolition had a demolition pemit for the apparrent demolition. A water source was seen and the site was fenced and screened. No dust was observed at this time.



Environmental Complaints

Date of	Complaint	Resolution	Inspector Comments
2/22/12	SR# 12-00283014	VALID	I responded to a complaint that suggested individuals were dumping waste in a garage. Upon arrival to the subject site I saw that this single family home has been abandon and the gas and water service terminated. DOB had also visited the site and placed a sign on the front door requesting people to stay out. In the rear of the house in the alley, I observed the garage filled with cardboard boxes and bags of CD waste. I title search will be conducted in an effort to identify the owner and have them remove the waste and secure the garage.



Environmental Complaints From Old Database

11200 S EDBROOKE AVE

Date Received	Facility	Code	Comments
12/7/99	Sang Wook RA	15	Fly dumping of tires & debris at the above loc. Garbage clothing, cardboard, boxes, & two tires dumped in open space dock in area.

Date Received	Facility	Code	Comments
6/27/97	Residential Area	09	Cars being worked on and motor oil is being change & dumped in the back of the garage & alley. Ground is oil stained & auto repair has taken place.



Environmental Code Enforcement From Old Database

Date	Company	Liable	Туре	Charge	Comments
2/24/00	Ra, Sang Wook	L	ADM	7-28-450 : Owner responsible for nuisance	
2/24/00	Ra, Sang Wook	L	ADM	7-28-720 : Accumlate junk atracting rats	



Asbestos Work Notification

11200 S EDBROOKE AVE

ENVGEN119567

Contact Name	Contact Capacity	Work Start	Work End
Ameri Environmental, Inc.	Operator	4/20/12	4/26/12
CITY OF CHICAGO	Owner	4/20/12	4/26/12

ENVGEN119568

Contact Name	Contact Capacity	Work Start	Work End
Ameri Environmental, Inc.	Operator	4/27/12	5/27/12
CITY OF CHICAGO	Owner	4/27/12	5/27/12
NF Demolition	Operator	4/27/12	5/27/12

11217 S EDBROOKE AVE

ENVGEN121996

Contact Name	Contact Capacity	Work Start	Work End
CITY OF CHICAGO	Owner		
N. F. DEMOLITION, INC	Operator		

11238 S EDBROOKE AVE

ENVGEN121876

Contact Name	Contact Capacity	Work Start	Work End
CITY OF CHICAGO	Owner		
Spirit Wrecking and Excavation	Operator		

Environmental FOIA Search Results



Asbestos Work Notification

Permit AP No	Document Link (Internal Office Use Only)
ENVGEN119567	http://dc07apw26/DOEATTACHMENTS/11200%20s%20edbrooke%20ACM.PDF
ENVGEN119568	http://dc07apw26/DOEATTACHMENTS/11200%20s%20edbrooke%20ACM.PDF
ENVGEN119568	http://dc07apw26/DOEATTACHMENTS/11200-32%20S%20Edbrooke%20Demo.PDF



Asbestos Notifications From Old Database

11153 S EDBROOKE

Notification Type: DEMO NOTICE OF INTENT

Notification Date: 3/27/1996





Asbestos Notifications From Old Database

11200 S EDBROOKE

Notification Type: DEMO NOTICE OF INTENT

Notification Date: 11/9/2000



Notification Date: 2/26/1999

	Owner		Contr	actor ID	Begin Da	te	Complete Date	
City of Chicago		NA01		3/10/1999				
RACM Area (SF)	RACM Volume (CF)	RACM Pipe (FT)		timated ste (CY)	Wast	e Hauler		Disposal Site
	0		80	cu yds.	Land	& Lakes	2	000 E. 122nd St.
Height (Ft) Lo	ength (Ft)	W	/idth (Ft)				
42	42 204 16		160					
Comments								



Asbestos Notifications From Old Database

11221 S EDBROOKE

Notification Type: DEMO NOTICE OF INTENT

Notification Date: 8/13/1996





Asbestos Notifications From Old Database

11223 S EDBROOKE

Notification Type: DEMO NOTICE OF INTENT

Notification Date: 8/5/2010





Asbestos Notifications From Old Database

11236 S EDBROOKE

Notification Type: DEMO NOTICE OF INTENT

Notification Date: 1/9/1998





The attached pages contain FOIA search results for the following addresses:

11147 to 11227 S MICHIGAN AVE

Results Summary

ltem	Current System*	Old System*
Permits	Х	NA
Inspections	Х	Х
Complaints		
Enforcement		Х
Tank Assets		Х
AST	Included in Tank Assets	
Air Equipment		See Current System
Asbestos		
LUST NFR**		NA
Highway Authority		

* The Current System contains information after 4thQ 2011. Records prior to 4thQ 2011 are generally found in the the Old System.

** CDPH only maintains NFR Letters from LUST cleanups. Records for SRP and all other NFRs can be obtained from the Chicago Department of Fleet and Facilities Management.

X - Records found.



Environmental Permits

11155 S MICHIGAN AVE

Added Date	Apname	Permit Number	Application Description
9/8/14	Chicago Emerald LLC	ENVAIR181108	DOE Air Quality

Added Date	Apname	Permit Number	Application Description
8/14/18	Residential	ENVAIR994520	DOE Air Quality



Environmental Inspections

11158 S MICHIGAN AVE

Date of Inspection	Inspection #	Inspection Type Description	Inspection Narrative
2020-10-08	1594642	Site Assesment	On October 8, 2020 Department of Public Health Inspector Dwight T-Kilgore inspected property at 11158 S. Michigan Ave. this property was listed as needing tuckpointing 450 SQFT, work looks as if it is not finish, will reinspect.
2020-12-21	1594643	Site Assesment	On December 21, 2020 Department of Public Health Inspector Dwight T-Kilgore inspected property at 11158 S. Michigan Ave. This property was schedule for tuckpointing 450 SQFT work is not done, will re-inspected.

	Date of Inspection	Inspection #	Inspection Type Description	Inspection Narrative
--	--------------------	--------------	--------------------------------	----------------------



Environmental Inspections

Date of Inspection	Inspection #	Inspection Type Description	Inspection Narrative
2019-06-11	1408886	Demo/NESHAPS	This was a demolition (building) which was underway, with the structure partially demolished and a worker in a machine getting loading into a truck. There were 2 openings in the site fence, missing fabric mesh on 1 section, and missing fence in one area. The street was blocked by CPD because of the size and other details about the demo. Photo A) opening Photo B) opening Photo D) missing fabric mesh Photo D) missing fence I spoke to the site supervisor – he stated that the CPD used the openings during the day and their presence would deter anyone from entering the site. He will add the missing fabric mesh and enclose the open portion of the site. I will monitor the site week by week.



Environmental Inspections

Date of Inspection	Inspection #	Inspection Type Description	Inspection Narrative
2019-08-28	1412265	Demo/NESHAPS	This demolition was underway, with the structure being demolished by workers in machines. The front of the building had been demolished or had collapsed into the street. They had moved the fence out to cover the area needing to be cleaned up. Photo A) fence in the street I expect the fence to be moved back once the debris is cleaned up, will check tomorrow that this has been done.
2019-09-13	1443358	Demo/NESHAPS	This demolition was partially done but no workers were present and no work being done. There was a gap in the fence on the street side that made the site accessible. Photo A) gap in the fence I will return to address this with the contractor.
2019-12-04	1485404	Demo/NESHAPS	The scheduled demolition has been completed and the site has been levelled to grade. Photo A) Site



Environmental Inspections

Date of Inspection	Inspection #	Inspection Type Description	Inspection Narrative
2019-08-27	1442412	Demo/NESHAPS	The scheduled demolition has been completed and the site has been levelled to grade. Photo A) Site



Environmental Inspections From Old Database

11147 S MICHIGAN AVE

Inspection Date	Site Name	Inspection Type	Comments
1999-08-26		A5	Visual
1999-08-05	Ranch Steak House	A5	Grease on ground around grease trap. Respondent caused or allowed the accumulation of garbage debris fefused.

11200 S MICHIGAN AVE

Inspection Date	Site Name	Inspection Type	Comments
1999-10-18		A8	

Inspection Date	Site Name	Inspection Type	Comments
1998-10-13	Giant Beauty Supply	A10	Company is in compliance. Observed dumpster for OCC 7 BBs for glass & cans.
1998-04-03	Giant Beauty Supply	A10	For failure to establish an effective recylcing program in commercial establishments.

Inspection Type	Description
A10	Building Recycling Program



Environmental Code Enforcement From Old Database

11147 S MICHIGAN AVE

Date	Company	Liable	Туре	Charge	Comments
8/5/99	Ranch Steack House	L	ADM	7-28-450 : Owner responsible for nuisance	PD 9/16/99
8/5/99	Ranch Steack House	L	ADM	7-28-720 : Accumlate junk atracting rats	PD 9/16/99

Date	Company	Liable	Туре	Charge	Comments
4/3/98	Giant Beauty Supply		ADM	11-5-023 : Commercial Bldg recycling program	



Tank Asset Information

Facility ID: 2036925

Company	Fullname	Capacity	Facility Phone
UNKNOWN	MR WON H KANG	Primary	

Facility ID Key

Facility ID	Address
2036925	11201 S MICHIGAN AVE



Pre-1992 USTs from Building Department

11151 S MICHIGAN AVE

Date Of Tank	Facility Name	Work By	Comments
1954-09-29	NEISNER DNOS ST	W & B TAUB COMPANY	INSTALL 1-1K GAL FUEL OIL TANK FINAL 6/8/55

11155 S MICHIGAN AVE

Date Of Tank	Facility Name	Work By	Comments
1947-09-23	THREE SISTERS	WATER TUBE	INSTALL 1-1K GAL FUEL OIL TANK
	STORE	BOILER & TANK	FINAL 9/26/47

11200 S MICHIGAN AVE

Date Of Tank	Facility Name	Work By	Comments
1955-08-12	NATIONAL CLOTHING	WATER TUBE BOILER & TANK	INSTALL/ENCLOSE 1-1K GAL FUEL OIL TANK FINAL N/G

Date Of Tank	Facility Name	Work By	Comments
1950-02-09	J. C. PENNEY COMPANY	SUMNER S. SOLLITT & COMPANY	INSTALL 1-15K GAL FUEL OIL TANK FINAL 10/13/50



UST Permit Information From Old Database

FACILITY ID: 2036925

Permit Number	Permit Type	lssued Date	Completion Date	# Tanks	Permit Location	Comments
101042	ABANDON	6/24/94				TANK CAN NOT BE LOCATED.
DATE			(COMMEN	NTS	

10/4/94 THE TANK WAS NOT LOCATED. INSTEAD TWO ABOVE GROUND STORAGE TANKS WERE FOUND AND REMOVED.

FACILITY ID KEY

Facility ID	Address
2036925	11201 S MICHIGAN AVE



P2 and Air Equipment

Application	Faci	lity	Permit No.	Date
DOE Air Quality	Residential		ENVAIR994520	9/4/18
			'	
EQUIPMENT ID	QUANTITY		DESCRIPTION	
	1	137	- EXHAUST HOOD FILTE	RED



Asbestos Work Notification

11201 S MICHIGAN AVE

ENVGEN1111744

Contact Name	Contact Capacity	Work Start	Work End
ALLIANCE DEMOLITION	Wreck	6/10/19	8/1/19
Katie Mccormick	Owner	6/10/19	8/1/19
Ryan Jensen	WebAppIcnt	6/10/19	8/1/19

11212 S MICHIGAN AVE

ENVGEN1081710

Contact Name	Contact Capacity	Work Start	Work End
CITY OF CHICAGO, DEPARTMENT OF BUILDINGS	Owner	4/5/19	4/8/19
KLF ENTERPRISES	Wreck	4/5/19	4/8/19
Sergio Zepeda	WebAppIcnt	4/5/19	4/8/19

ENVGEN1147831

Contact Name	Contact Capacity	Work Start	Work End
CITY OF CHICAGO, DEPARTMENT OF BUILDINGS	Owner	8/22/19	9/5/19
KLF ENTERPRISES	Wreck	8/22/19	9/5/19
Sergio Zepeda	WebAppIcnt	8/22/19	9/5/19



Asbestos Work Notification

Permit AP No	Document Link (Internal Office Use Only)
ENVGEN1081710	http://dc07apw26/DOEATTACHMENTS/klf-scan-0151.pdf
ENVGEN1081710	http://dc07apw26/DOEATTACHMENTS/klf-scan-0152.pdf
ENVGEN1111744	http://dc07apw26/DOEATTACHMENTS/11201%20S%20Michigan%20Env.pdf
ENVGEN1111744	http://dc07apw26/DOEATTACHMENTS/11201%20S%20Michigan%20proceed%20.pdf
ENVGEN1147831	http://dc07apw26/DOEATTACHMENTS/klf-scan-0832.pdf
ENVGEN1147831	http://dc07apw26/DOEATTACHMENTS/klf-scan-0833.pdf
ENVGEN1147831	http://dc07apw26/DOEATTACHMENTS/klf-scan-0847.pdf